

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE 764  
COLUMBIA, SOUTH CAROLINA 29218

O. W. DIXON, JR.  
VICE PRESIDENT  
NUCLEAR OPERATIONS

February 25 21 10 1984  
83 FEB 25 21 10 1984

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Region II, Suite 3100  
101 Marietta Street, N.W.  
Atlanta, Georgia 30303

SUBJECT: Virgil C. Summer Nuclear Station  
Docket No. 50/395  
Operating License No. NPF-12  
Thirty Day Written Report  
LER 83-008

Dear Mr. O'Reilly:

Please find attached Licensee Event Report #83-008 for Virgil C. Summer Nuclear Station. This Thirty Day Report is required by Technical Specification 6.9.1.13.(b) as a result of entry into Action Statement 15 of Technical Specification 3.3.2, "Engineered Safety Feature Actuation System Instrumentation," on January 27, 1983.

Should there be any questions, please call us at your convenience.

Very truly yours,



O. W. Dixon, Jr.

CJM:OWD:dwf/fjc  
Attachment

cc: V. C. Summer  
T. C. Nichols, Jr.  
E. C. Roberts  
O. W. Dixon, Jr.  
H. N. Cyrus  
H. T. Babb  
D. A. Nauman  
M. B. Whitaker, Jr.  
W. A. Williams, Jr.  
O. S. Bradham  
R. B. Clary  
C. A. Price

A. R. Koon  
G. D. Moffatt  
Site QA  
C. L. Ligon (NSRC)  
G. J. Braddick  
J. L. Skolds  
J. B. Knotts, Jr.  
B. A. Bursey  
I&E (Washington)  
Document Management Branch  
INPO Records Center  
NPCF  
File

8303010449 830221  
PDR ADOCK 05000395  
S PDR

OFFICIAL COPY  
18 22

Mr. James P. O'Reilly  
LER No. 83-008  
Page Two  
February 21, 1983

#### DETAILED DESCRIPTION OF EVENT

On January 27, 1983, with the Plant in Mode 1, the Main Control Board indication (PI-486) for Steam Generator "B" Steam Pressure decreased approximately 100 psig as compared to redundant channels. The "Steam Line Hi DP" alarm was also received at the time of the observed discrepancy in pressure indication. The channel was declared inoperable at 0800 hours, and the bistables placed in the trip condition within one (1) hour in compliance with Action Statement 15 of Technical Specification 3.3.2.

#### PROBABLE CONSEQUENCES

There were no adverse consequences as SCE&G complied with the Action Statement of the applicable Technical Specification.

#### CAUSE(S) OF THE OCCURRENCE

The cause of the occurrence is attributed to a plugged transmitter sensing line.

#### IMMEDIATE CORRECTIVE ACTIONS TAKEN

The inoperable channel was placed in the tripped condition within one (1) hour in accordance with Action Statement 15 of Technical Specification 3.3.2. The initial investigation indicated that the failure of pressure transmitter PT-486 to reflect the process pressure was due to a plugged sensing line. The sensing line blockage was cleared by applying back pressure through the transmitter valve manifold. Steam Generator "B" Steam Pressure indication returned to normal upon the completion of the flushing activity. The channel was declared operable at 1125 hours on January 27, 1983, upon the satisfactory performance of a Channel Check.

#### ACTION TAKEN TO PREVENT RECURRENCE

The licensee plans no further action in regards to this isolated event other than the normal surveillance testing.