

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 P A S E S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CONT

01 REPORT SOURCE L 6 5 0 0 0 0 3 8 7 7 0 2 0 8 8 3 8 0 2 2 2 8 3 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During the performance of a Startup Test, it was determined that the total

03 runout flow on the feedwater pumps was in excess of the assumed value stated

04 in the FSAR. This is reportable per Technical Specification 6.9.1.8.i. There

05 were no adverse consequences in that the feedwater controllers functioned

06 properly throughout the test program to date, thus not subjecting the

07 unit to the described transient.

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
Z Z 11 X 12 Z 13 Z Z Z Z Z Z 14 Z 15 Z 16

17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
8 3 0 1 0 0 1 T 0

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
E 18 Z 19 Z 20 Z 21 0 0 0 0 0 Y 23 N 24 Z 25 Z 9 9 9 9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Due to changes in plant parameters between the time when the feed pump turbine

11 stops were set and achieving 100% power, the stop settings did not restrict

12 the maximum feedwater runout capability to the value stated in the FSAR.

13 Using more accurate data, the stops were reset. There are no further cor-

14 rective actions.

15 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
B 28 0 9 6 29 n/a C 31 engineering evaluation

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
Z 33 Z 34 n/a n/a

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
0 0 0 37 Z 38 n/a

18 PERSONNEL INJURIES NUMBER DESCRIPTION (41)
0 0 0 40 n/a

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)
Z 42 n/a

20 PUBLICITY ISSUED DESCRIPTION (45)
N 44 n/a

NRC USE ONLY

Attachment

Licensee Event Report 83-010/01T-0

After the turbine trip test at 75% power, the feed pump turbine stops were set at a calculated value which would prevent feed pump trips due to low suction pressure. Due to differences in turbine steam inlet pressure, suction pressure, and back pressure between 75% and 100% power, an accurate determination of maximum feedwater runout capability could not be made. 100% power provided the best normal operating condition to estimate maximum feedwater runout capability.

Using the data collected in a subsequent Startup Test, the stops were reset. Appropriate retesting demonstrated that the feedwater flow runout capability was properly limited.

LAK/cg