

**LICENSEE EVENT REPORT**

U. S. NUCLEAR REGULATORY COMMISSION  
UPDATED REPORT  
PREVIOUS REPORT DATE: 1/19/83

CONTROL BLOCK: 

--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	I	L	D	R	S	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58	

CON'T

REPORT SOURCE L 6 0 5 0 0 0 2 3 7 7 0 1 0 3 8 3 8 0 2 1 0 8 3 9

60 61 DOCKET NUMBER 66 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operation with DOS 1500-1 (LPCI Valve Operability Test) in progress,

03 MO 2-1501-19A failed to close (Tech. Spec. 3.7.D.2). Safety significance was minimal

04 | since valve MO 2-1501-18A was operable and closed in line with MO 2-1501-19A to pro-

05 vide isolation. There was no effect on public health or safety. Previous occurrence

06 lof valve failure reported by R.O. 82-26 and 82-53 on Docket 50-237.

07

08 | \_\_\_\_\_

7 8 9 10 11 12 13 14 15 16

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

0 9 S F E A C K T B R K B Z

(17) LER/RO REPORT NUMBER EVENT YEAR  
82—  
21 22 23

SEQUENTIAL REPORT NO. 002/  
24 25 26 27

OCCURRENCE CODE 03  
28 29

REPORT TYPE X—  
30 31

REVISION NO. 1  
32

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
B	18	Z	19	Z	20	Z	21	0	0	0	0	N	22	Y	23	N	24	G	0	8	0
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Cause of the event was a loose wire (19A-CR109C0) in the combination starter. The

1 1 terminal was tightened and valve was successfully cycled from the control room. Work,

request was initiated to inspect the contactor. No additional loose wires were dis-

1 3 covered during this inspection." One third of all safety related 480V MCC contactors,

4 (DMP 7300-5) are inspected each refueling outage. DOS 1500-1 is performed monthly.

FACILITY STATUS (28) 1 5 E  
 TOWER 0 3 4 (29)  
 OTHER STATUS (30) N/A  
 METHOD OF DISCOVERY (31) B  
 DISCOVERY DESCRIPTION (32) Routine Surveillance

ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	6	Z	33	Z	34	N/A	N/A

PERSONNEL EXPOSURES										
NUMBER		TYPE		DESCRIPTION						
1	7	0	0	0	(37) Z	(38)	N/A			

PERSONNEL INJURIES						80
NUMBER		DESCRIPTION				
0	0	0	(40)	N/A		

8	9	11	12	80
LOSS OF OR DAMAGE TO FACILITY (43)				
TYPE	DESCRIPTION			

8303080099 830210  
PDR ADPOCK 05000237

2 0 N 44 N/A S PDR PDR  
8 9 10 58 69 30  
NAME OF PREPARED L. Coyle 815-942-2920. X-526

NAME OF PREPARER

L. Covle

PHONE:

815-942-2920, X-526

# SUPPLEMENT TO DVR

DVR NO.	STA	UNIT.	YEAR	NO.
D - 12 - 2 - 83 - 2				

<b>PART 1</b>	<b>TITLE OF EVENT</b>	<b>OCCURRED</b>	
	Failure of LPCI Valve 2-1501-19A To Close	1/3/83	2200
		<b>DATE</b>	<b>TIME</b>
	<b>REASON FOR SUPPLEMENTAL REPORT</b>		
	A change in future actions.		
<b>PART 2</b>			
	<b>ACCEPTANCE BY STATION REVIEW</b>	<i>J. Brunner</i>	<i>W. M. Almon</i>
	<b>DATE</b>	2/16/83	2/16/83
	<b>SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION</b>	<i>Douglas D. ...</i>	2/16/83
		<b>STATION SUPERINTENDENT</b>	<b>DATE</b>