

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	7	
---	---	--

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRO-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
B	18	H	19	Z	20	Z	21	0	0	0	0	Y	22	Y	24	A	25
32	34	35	36	37	40	41	42	43	44	45	46	47	48	49	50	51	52

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

EVERY EFFORT WILL BE MADE TO PREVENT FUTURE DAMAGE TO THE HINGES. SEE SUPPLEMENT.

10
PUBLICITY
ISSUED DESCRIPTION (45)
20 NA

PHCNE: 616-465-5901

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

70 OF 192 DOORS EXCEEDED THE MAXIMUM INITIAL OPENING FORCE SPECIFICATIONS DUE TO MISALIGNED AND/OR DENTED HINGES. IT IS BELIEVED THAT THE HINGES HAD BECOME MISALIGNED AND DENTED DURING ICE BED MAINTENANCE AND SURVEILLANCE ACTIVITIES. THE HINGES WERE REALIGNED AND LUBRICATED. THE DOORS WERE RE-TESTED AND RESULTS WERE ACCEPTABLE. IN THE FUTURE, EVERY EFFORT WILL BE MADE TO PREVENT DAMAGE TO THE INTERMEDIATE DECK DOOR HINGES DURING ICE BASKET WEIGHING AND ICE ADDITION. PERSONNEL INVOLVED WITH THESE ACTIVITIES WILL BE CAUTIONED TO MINIMIZE CONTACT WITH THE HINGES. DIFFERENT METHODS FOR DETERMINING THE WEIGHT OF THE ICE BASKETS ARE BEING INVESTIGATED. SHOULD IT BE APPARENT DURING FUTURE SURVEILLANCE WORK THAT HINGE DAMAGE MAY HAVE OCCURRED THE INTERMEDIATE DECK DOOR SURVEILLANCE PROCEDURE WILL BE PERFORMED FOLLOWING THESE ACTIVITIES AND PRIOR TO RETURNING THE ICE CONDENSER TO OPERABLE STATUS.