

UPDATE
LICENSEE EVENT REPORT

U. S. NUCLEAR REGULATORY COMMISSION

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 NYJAF1 200-0000-000 341111 4 5
7 8 9 14 15 25 26 57 CAT 58

CON'T
01 REPORT SOURCE L 6 0500033 7 052082 8 022583 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operation, following surveillance, Residual Heat Removal Service
03 Water (RHRSW) Pump 'A' discharge check valve stuck open at the completion of pump
04 testing. The pump was declared inoperable when required by TS 3.5.B.1. Other RHR
05 components were tested with satisfactory results as required by TS 4.5.B.2. No
06 significant hazard existed.

07
08

09
SYSTEM CODE SH 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE VALVEX 14
COMP. SUBCODE C 15 VALVE SUBCODE A 16
17 LER/RO REPORT NUMBER 82 21 22 024 24 26 27 03 28 29 30 L 31 32 1 33
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED Y 23 NPSD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER V085 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 As presented in Revision 0, inspection of the other Residual Heat Removal Service
11 Water (RHRSW) and Emergency Service Water (ESW) pump discharge check valves was
12 performed with the following results and corrective action.

13
14

15 FACILITY STATUS E 28 % POWER 100 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 Surveillance 32 DISCOVERY DESCRIPTION
7 8 9 10 12 13 44 45 46 80
16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
7 8 9 10 11 44 45 80
17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
7 8 9 10 11 12 13 44 45 80
18 PERSONNEL INJURIES NUMBER DESCRIPTION 41
7 8 9 10 11 12 13 44 45 80

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43 8303090195 830225 PDR ADDOCK 05000333 PDR
7 8 9 10 11 12 44 45 80
20 PUBLICITY ISSUED DESCRIPTION 45 NA
7 8 9 10 11 12 44 45 80

21
22

23
24

NAME OF PREPARER William Fernandez

PHONE

315 342-3840

NRC USE ONLY

POWER AUTHORITY OF THE STATE OF NEW YORK
JAMES A. FITZPATRICK NUCLEAR POWER PLANT

DOCKET NO. 50-333

ATTACHMENT TO LER 82-024/03L-1

PAGE 1 of 1

1. 10 RHR 14B (Inspected 10/15/82)

Our letter, MD-82-053, commits to a final maintenance recommendation to prevent recurrence.

2. 10 RHR 14C (Inspected 2/7/83)

10 RHR 14A - 10/17705 (5/20/82) Valve would not shut. Found that cotter pin was missing (probably rusted away), disc nut had backed off. Replaced disc nut and washer, installed stainless steel cotter pin.

3. 10 RHR 14D (Inspected 10/15/82)

10 RHR 14B - 10/16208 (10/15/82) Inspected valve. Found that cotter pin was missing. No other problems. Installed stainless steel cotter pin.

4. 46 ESW 1A (Inspected 10/22/82)

10 RHR 14D - 10/16209 (10/15/82) Inspected valve. Found no problems. Replaced carbon steel cotter pin with stainless steel.

5. 46 ESW 1B (Inspected 10/15/82)

46 ESW 1B - 46/16222 (10/15/82) Inspected valve. Found no problems. Replaced carbon steel cotter pin with stainless steel.