

LICENSEE EVENT REPORT

CONTROL BLOCK:

| | | | | | |
|--|--|--|--|--|--|
| | | | | | |
|--|--|--|--|--|--|

 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---------------|---|---|---|---|---|----|----|----------------|---|---|---|---|---|---|---|---|---|----|----|--------------|---|---|---|---|----|----|--------|--|
| 0 | 1 | N | Y | J | A | F | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | | | 5 | |
| 7 | 8 | LICENSEE CODE | | | | | | 14 | 15 | LICENSE NUMBER | | | | | | | | | | 25 | 26 | LICENSE TYPE | | | | | 30 | 57 | CAT 58 | |

CON'T

0 1 7 8

REPORT SOURCE L 6 0 5 0 0 0 3 3 3 7 0 5 2 0 8 2 8 0 3 0 3 8 3 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

| | | |
|---|---|---|
| 0 | 2 | During normal operation, following surveillance, Residual Heat Removal Service |
| 0 | 3 | Water (RHRSW) Pump 'A' discharge check valve stuck open at the completion of pump |
| 0 | 4 | testing. The pump was declared inoperable when required by T.S. 3.5.B.1. Other |
| 0 | 5 | RHR components were tested with satisfactory results as required by T.S. 4.5.B.2. |
| 0 | 6 | No significant hazard existed. |
| 0 | 7 | |
| 0 | 8 | |

| | | | | | | | | | | | | | | | | | |
|-----------------------|--|--------------------------------|--|-------------------------|--|----------------------------------|--|-----------------------|--|------------------------------|--|--------------------------|--|------------------------------|--|--------------------------------------|--|
| SYSTEM CODE S H 11 | | CAUSE CODE E 12 | | CAUSE SUBCODE B 13 | | COMPONENT CODE V A L V E X 14 | | COMP. SUBCODE C 15 | | VALVE SUBCODE A 16 | | | | | | | |
| EVENT YEAR 8 2 | | SEQUENTIAL REPORT NO. 0 2 4 | | OCCURRENCE CODE 0 3 | | REPORT TYPE L | | REVISION NO. 2 | | | | | | | | | |
| ACTION TAKEN A 18 | | FUTURE ACTION X 19 | | EFFECT ON PLANT Z 20 | | SHUTDOWN METHOD Z 21 | | HOURS 0 0 0 0 22 | | ATTACHMENT SUBMITTED Y 23 | | NPRD-4 FORM SUB. Y 24 | | PRIME COMP. SUPPLIER A 25 | | COMPONENT MANUFACTURER V 0 8 5 26 | |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

As presented in Revision 0, inspection of the other Residual Heat Removal Service Water (RHRSW) and Emergency Service Water (ESW) pump discharge check valves was performed with the following results and corrective actions. Revision 1 attachment was in error; Revision 2 rectifies the errors.

7 8 9
FACILITY STATUS (28) 1 5 E
% POWER 1 0 0 (29) 10 11 12
OTHER STATUS (30) NA 13 44
METHOD OF DISCOVERY (31) B
DISCOVERY DESCRIPTION (32) Surveillance 45 46 80

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 33 2 34

AMOUNT OF ACTIVITY NA 35

LOCATION OF RELEASE NA 36

| PERSONNEL EXPOSURES | | TYPE | | DESCRIPTION |
|---------------------|---|------|---|-------------|
| NUMBER | | | | |
| 1 | 7 | 0 | 0 | 0 |
| | | (37) | Z | (38) NA |

| PERSONNEL INJURIES | | DESCRIPTION | |
|--------------------|---|-------------|---|
| NUMBER | | | |
| 1 | 0 | 0 | 0 |
| 2 | 0 | 0 | 0 |
| 3 | 0 | 0 | 0 |
| 4 | 0 | 0 | 0 |
| 5 | 0 | 0 | 0 |
| 6 | 0 | 0 | 0 |
| 7 | 0 | 0 | 0 |
| 8 | 0 | 0 | 0 |
| 9 | 0 | 0 | 0 |
| 10 | 0 | 0 | 0 |
| 11 | 0 | 0 | 0 |
| 12 | 0 | 0 | 0 |
| 13 | 0 | 0 | 0 |
| 14 | 0 | 0 | 0 |
| 15 | 0 | 0 | 0 |
| 16 | 0 | 0 | 0 |
| 17 | 0 | 0 | 0 |
| 18 | 0 | 0 | 0 |
| 19 | 0 | 0 | 0 |
| 20 | 0 | 0 | 0 |
| 21 | 0 | 0 | 0 |
| 22 | 0 | 0 | 0 |
| 23 | 0 | 0 | 0 |
| 24 | 0 | 0 | 0 |
| 25 | 0 | 0 | 0 |
| 26 | 0 | 0 | 0 |
| 27 | 0 | 0 | 0 |
| 28 | 0 | 0 | 0 |
| 29 | 0 | 0 | 0 |
| 30 | 0 | 0 | 0 |
| 31 | 0 | 0 | 0 |
| 32 | 0 | 0 | 0 |
| 33 | 0 | 0 | 0 |
| 34 | 0 | 0 | 0 |
| 35 | 0 | 0 | 0 |
| 36 | 0 | 0 | 0 |
| 37 | 0 | 0 | 0 |
| 38 | 0 | 0 | 0 |
| 39 | 0 | 0 | 0 |
| 40 | 0 | 0 | 0 |
| 41 | 0 | 0 | 0 |
| 42 | 0 | 0 | 0 |
| 43 | 0 | 0 | 0 |
| 44 | 0 | 0 | 0 |
| 45 | 0 | 0 | 0 |
| 46 | 0 | 0 | 0 |
| 47 | 0 | 0 | 0 |
| 48 | 0 | 0 | 0 |
| 49 | 0 | 0 | 0 |
| 50 | 0 | 0 | 0 |
| 51 | 0 | 0 | 0 |
| 52 | 0 | 0 | 0 |
| 53 | 0 | 0 | 0 |
| 54 | 0 | 0 | 0 |
| 55 | 0 | 0 | 0 |
| 56 | 0 | 0 | 0 |
| 57 | 0 | 0 | 0 |
| 58 | 0 | 0 | 0 |
| 59 | 0 | 0 | 0 |
| 60 | 0 | 0 | 0 |
| 61 | 0 | 0 | 0 |
| 62 | 0 | 0 | 0 |
| 63 | 0 | 0 | 0 |
| 64 | 0 | 0 | 0 |
| 65 | 0 | 0 | 0 |
| 66 | 0 | 0 | 0 |
| 67 | 0 | 0 | 0 |
| 68 | 0 | 0 | 0 |
| 69 | 0 | 0 | 0 |
| 70 | 0 | 0 | 0 |
| 71 | 0 | 0 | 0 |
| 72 | 0 | 0 | 0 |
| 73 | 0 | 0 | 0 |
| 74 | 0 | 0 | 0 |
| 75 | 0 | 0 | 0 |
| 76 | 0 | 0 | 0 |
| 77 | 0 | 0 | 0 |
| 78 | 0 | 0 | 0 |
| 79 | 0 | 0 | 0 |
| 80 | 0 | 0 | 0 |
| 81 | 0 | 0 | 0 |
| 82 | 0 | 0 | 0 |
| 83 | 0 | 0 | 0 |
| 84 | 0 | 0 | 0 |
| 85 | 0 | 0 | 0 |
| 86 | 0 | 0 | 0 |
| 87 | 0 | 0 | 0 |
| 88 | 0 | 0 | 0 |
| 89 | 0 | 0 | 0 |
| 90 | 0 | 0 | 0 |
| 91 | 0 | 0 | 0 |
| 92 | 0 | 0 | 0 |
| 93 | 0 | 0 | 0 |
| 94 | 0 | 0 | 0 |
| 95 | 0 | 0 | 0 |
| 96 | 0 | 0 | 0 |
| 97 | 0 | 0 | 0 |
| 98 | 0 | 0 | 0 |
| 99 | 0 | 0 | 0 |
| 100 | 0 | 0 | 0 |

| | | LOSS OF OR DAMAGE TO FACILITY | | | | | | (43) |
|---|---|-------------------------------|------|----|--|--|--|------|
| | | TYPE DESCRIPTION | | | | | | |
| 1 | 9 | 7 | (42) | NA | | | | |

7 8 9 10
PUBLICITY
ISSUED DESCRIPTION (45) NA
8303140507 830303
PDR AD0CK 05000333 PDR
NRC USE ONLY

NAME OF PREPARER William Fernandez PHONE: (315) 342-38

POWER AUTHORITY OF THE STATE OF NEW YORK
JAMES A. FITZPATRICK NUCLEAR POWER PLANT

DOCKET NO. 50-333

ATTACHMENT TO LER 82-024/03L-2

PAGE 1 of 1

1. 10 RHR 14B 10/16208 (Inspected 10/15/82)

Inspected valve. Found that cotter pin was missing. No other problems. Installed stainless steel cotter pin.

2. 10 RHR 14C 10/16210 (Inspected 2/7/83)

Inspected valve. Found disc nut partially eroded away. No other problems. Replaced disc nut. Replaced carbon steel cotter pin with stainless steel.

3. 10 RHR 14D 10/16209 (Inspected 10/15/82)

Inspected valve. Found no problems. Replaced carbon steel cotter pin with stainless steel.

4. 46 ESW 1A 46/16221 (Inspected 10/22/82)

Inspected valve. Found disc stud corroded. No other problems. Replaced carbon steel cotter pin with stainless steel. Ordered new disc.

5. 46 ESW 1B 46/16222 (Inspected 10/15/82)

Inspected valve. Found no problems. Replaced carbon steel cotter pin with stainless steel.