



**PUBLIC
SERVICE
INDIANA**

S. W. Shields
Senior Vice President -
Nuclear Division

March 8, 1983
S82-25
SVP-0013-83

Mr. James G. Keppler,
Regional Administrator
U. S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Docket Nos.: STN 50-546
STN 50-547
Construction Permit Nos.:
CPPR - 170
CPPR - 171

Marble Hill Nuclear Generating Station - Units 1 and 2


Dear Mr. Keppler:

On October 20, 1982, Mr. T. D. Geib of Public Service Company of Indiana, Inc. (PSI) notified your office of a potentially reportable item as required by 10 CFR 50.55(e). During repair of spalled concrete around an embedded plate, deformed wire anchors were discovered to have separated from the plate. This item varies from that identified on August 18, 1982, since this embedded plate was installed after the resumption of safety related work at Marble Hill. Also, the scope of this problem is limited to separation of the wire anchors from the plate and at this time does not involve missing wires, nicked wires or wires bent beyond acceptable limits.

PSI is presently investigating the cause of plate/wire anchor separation and will factor the results of this investigation into the development of a technique for examining the condition of deformed wire anchors on installed embedded plates.

This letter is intended to fulfill the requirements of an interim report as defined in 10 CFR 50.55(e). A further report will be filed on or before June 10, 1983. If you have any questions regarding this matter please contact me at your convenience.

Sincerely,


S. W. Shields

8303150123 830308
PDR ADOCK 05000546
S PDR

SWS/LGY/bak

1E27

MAR 10 1983



Letter: J. G. Keppler

-2-

March 8, 1983
S82-25
SVP-0013-83

cc: Director of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

J. E. Konklin
J. J. Harrison