

No. 3 -83-03/3L

This L.E.R. concerns a Unit 3 electrical (E23) bus lock out due to an HEA relay failure. The applicable Tech. Spec. is 3.9.B.3.

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 P A P B S 3 2 0 0 - 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T 0 1 REPORT SOURCE 6 0 5 0 - 0 2 7 8 7 0 1 2 7 8 3 8 0 2 2 5 8 3 9

DOCKET NUMBER 60 61 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 0 2 During normal operation, an HEA relay on the E23 Emergency Safeguard

0 3 bus tripped the normal supply and locked out the backup and diesel

0 4 supplies. The E234 Emerg. Aux. Load Center De-energized and tripped the

0 5 offgas air ejector which resulted in reducing the condenser vacuum. Unit 3

0 6 operated for about 20 minutes with the E23 Bus locked out. Operators

0 7 manually scrammed Unit 3 in anticipation of a low vacuum scram. The

0 8 applicable Tech. Spec. is 3.9.B.3.

SYSTEM CODE E B 11 CAUSE CODE X 12 CAUSE SUBCODE Z 13 COMPONENT CODE Z Z Z Z Z Z Z 14 COMP SUBCODE Z 15 VALVE SUBCODE Z 16

LER-RO REPORT NUMBER 17 1 8 3 EVENT YEAR 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ACTION TAKEN X 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 0 1 2 3 4 5 6 7 8 9 0 1 2 3 4