

LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
C A S O S 3 2 0 0 - 0 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 1 4																																																																																																			
C 1										REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE																																																											

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
On January 23, 1983 at 0331 while in Mode 3, Channel A level indicator 3LI-1113-1 for										Steam Generator E-089 was declared inoperable when it failed its Technical Specification										Surveillance per Section 4.3.2.1. LCO 3.3.2 was invoked. As required by the Action Statement										associated with this LCO, the channel was immediately placed in the bypassed condition.										Since the ESFAS contains 4 channels for steam generator level indication and only 3										channels (all of which remained functional throughout the event) are required for operab-										ility, there was no impact on plant operation or the health and safety of plant personnel										or the public.																													

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
SYSTEM CODE										CAUSE CODE										CAUSE SUBCODE										COMPONENT CODE										COMP SUBCODE										VALVE SUBCODE																																																	
I B 11										X 12										Z 13										I N S T R U 14										I 15										Z 16																																																	
EVENT YEAR										SEQUENCE REPORT NO										OCCURRENCE CODE										REPORT TYPE										REVISION NO																																																											
8 3										0 0 8										0 3										L										0																																																											
ACTION TAKEN										EFFECT ON PLANT										SHUT-DOWN METHOD										HOURS										ATTACHMENT SUBMITTED										NPR-4 FORM SUB										PRIME COMP SUPPLIER										COMPONENT MANUFACTURER																													
E 18										Z 19										Z 20										0 0 0 0										N 23										N 24										N 25										S 1 8 5																													

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
Inoperability of the indicator was attributable to normal instrument drift. The										indicator was recalibrated and returned to service in accordance with Procedure										S023-3-3.25 on January 27, 1983. No further action is planned.																																																																															

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
FACILITY STATUS										POWER										OTHER STATUS										METHOD OF DISCOVERY										DISCOVERY DESCRIPTION																																																											
B 28										0 0 0 0										NA										B 31										Surveillance Testing																																																											
ACTIVITY RELEASED										CONTENT										AMOUNT OF ACTIVITY										LOCATION OF RELEASE																																																																					
Z 33										Z 34										NA										NA																																																																					
PERSONNEL EXPOSURES										TYPE										DESCRIPTION																																																																															
0 0 0 0										Z 38										NA																																																																															
PERSONNEL INJURIES										DESCRIPTION																																																																																									
0 0 0 0										NA																																																																																									
LOSSES OF OR DAMAGE TO FACILITY										TYPE										DESCRIPTION																																																																															
Z 42										NA																																																																																									
PUBLICITY										DESCRIPTION																																																																																									
N 44										NA																																																																																									

8303110092 830222
PDR ADOCK 05000362
S PDR

H. B. Ray

NRC USE ONLY

714/492-7700