

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | |

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A L B R F 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58 59

CONT
0 1 REPORT SOURCE L 6 0 5 0 0 0 2 6 0 7 1 0 0 3 8 1 3 0 2 1 9 8 2 6
7 8 9 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES
		During normal operation, containment atmosphere torus hydrogen analyzer 2-H ₂ M-76-104

 was removed from service for corrective maintenance and was declared inoperable.

(T.S. 3.7.H.2) There was no danger to the health or safety of the public. Redundant

 systems were available and operable. There were no previous similar events.

0 9

S A 11

E 12

X 13

I N S T R U 14

E 15

Z 16

(17) REPORT NUMBER	81	—	050	/	03	X	—	1				
	21	22	23	24	25	26	27	28	29	30	31	32

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB	PRIME SUPPLIER	COMPONENT MANUFACTURER
1	2	3	4	5	6	7	8	9
1	2	3	4	5	6	7	8	9

22 D 18 24 X 19 25b 26 Z 27 0 9 0 0 28 40 29 Y 30 31 N 32 33 34 35 A 36 37 38 39 40

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)

Water was found in the sensing lines and was removed. The Hayes-Republic hydrogen

monitor (2-H₂M-76-104) and the hydrogen analyzer were returned to service. Recurrence

control is being analyzed and a followup report will be issued by April 20, 1982.

STATUS		POWER		OTHER STATUS		DISCOVERY		DISCOVERY DESCRIPTION	
1	2	E	0	9	9	NA	B	11	Routine maintenance

1 6 Z 33 Z 34 NA NA

[illegible]

0 0 0 NA

10-750 (Rev. 11-79) NAG USE ONLY

PAGE		NUMBER		DESCRIPTION		DATE	
1	1	N	11	NA			

8203080487 820219
888-18224 05000240 Gene Holder (205) 720-6124

LER SUPPLEMENTAL INFORMATION

DFRO-50- 260 / 81050 R1 Technical Specification Involved 3.7.H.2.

Reported Under Technical Specification 6.7.2.b(2) * Date Due NRC NA

Date of Occurrence 10/3/81 Time of Occurrence 2345 Unit 2

Identification and Description of Occurrence:

Containment atmosphere torus hydrogen analyzer 2-H₂M-76-104 was removed from service for maintenance and was declared inoperable.

Conditions Prior to Occurrence:

Unit 1 in routine startup operations.

Unit 2 at 99%.

Unit 3 at 94%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Water in sensing lines of the hydrogen monitor.

Analysis of Occurrence:

There was no effect on the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

The water was removed from the sensing lines of the Hayes-Republic hydrogen monitor and the hydrogen analyzer was returned to service. Recurrence control is being analyzed and a followup report will be issued by April 20, 1982.

Failure Data: None

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: *John J. [Signature]*