

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1	N	Y	I	P	S	2	7	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
8	9	LICENSEE CODE				14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	57	CAT	58

N'T

1 8
REPORT SOURCE L 6 0 5 0 0 0 2 4 7 7 0 4 1 3 8 3 8 0 5 1 3 8 3 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2] During performance of Inservice Valve Test P.T.O.13, Valve 887B in the suction line
3] to No. 22 Safety Injection Pump was found to be inoperative.. Series Valve 887A was
4] determined to be operable. The valve was repaired and retested satisfactorily and
5] returned to service within the time period allowed by Tech. Spec. 3.3.A.2.d. The
6] health and safety of the public were unaffected.
7]
8]

9		SYSTEM CODE S F 11		CAUSE CODE E 12		CAUSE SUBCODE A 13		COMPONENT CODE V A L V O P 14		COMP. SUBCODE A 15		VALVE SUBCODE Z 16	
17 LER/RO REPORT NUMBER		EVENT YEAR 8 3 21 22		SEQUENTIAL REPORT NO. 1 1 24 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32			
ACTION TAKEN B 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED N 23		NPRD-4 FORM SUB. Y 24	
PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER L 2 0 0 26											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

0 A pinched and grounded wire for the motor (ID No.720343-WB) on the valve Limitorque
1 operator (type SMB-00) was determined to be the cause of failure. The wire was repaired,
2 the valve tested satisfactorily and was returned to service.
3
4

8 9		FACILITY STATUS		% POWER		OTHER STATUS (30)		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION (32)		80
5	28	1	0	0	29	NA	44	B	31	Surveillance Tests	46	80
8 9		ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY (35)				LOCATION OF RELEASE (36)		80
6	33	Z	34	NA	44	NA	45					80

PERSONNEL EXPOSURES											
NUMBER			TYPE	DESCRIPTION							
7	0	0	0	37	Z	38	NA				39

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
0	0	0	NA

8	9	11	12		
LOSS OF OR DAMAGE TO FACILITY				(43)	
TYPE		DESCRIPTION			
1Z	(43)	NA			
8305250483 830513					
PDR ADOCK 05000247					
S PDR					

19	42	101											80	
8	9	10												
PLURAL CITY														
ISSUED	DESCRIPTION	45												
0	N	41	NA											
8	9	10												
NRC USE ONLY														
<div style="display: flex; justify-content: space-between;"> 58 59 60 </div>														

NRC USE ONLY

John D. O'Toole
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

May 13, 1983

Re: Indian Point Unit No. 2
Docket No. 50-247
LER-83-011/03L-0


Mr. Thomas E. Murley,
Regional Administrator-Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

Dear Mr. Murley:

The attached Licensee Event Report LER-83-011/03L-0 is hereby submitted in accordance with the requirements of Technical Specification 6.9.1.7. This event is of the type described in Technical Specification 6.9.1.7.2.b.

Three copies of this letter and attachment are enclosed as required.

Very truly yours,



attach.

cc: Mr. Richard DeYoung, Director (30 copies)
Office of Inspection and Enforcement
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. William G. McDonald, Director (3 copies)
Office of Management Information and Program Control
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Thomas Foley, Senior Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, New York 10511

IE22