



SUPPLEMENTARY INFORMATION

Report No.: 50-302/82-005/03L-0

Facility: Crystal River Unit 3

Report Date: February 12, 1982

Occurrence Date: January 19, 1982

Identification of Occurrence:

Meteorological Monitoring Instrumentation Channels were out of tolerance, contrary to Technical Specification 3.3.3.4.

Conditions Prior to Occurrence:

Mode 1 power operations (100%).

Description of Occurrence:

At 1500, on January 19, 1982, during normal operation, the 175' and 33' wind direction and the 175' and 33' temperature channels of the Meteorological Monitor System was found to be out-of-tolerance while performing Surveillance Procedure SP-158.

Designation of Apparent Cause:

The cause of this event can be attributed to instrument drift.

Analysis of Occurrence:

There was no effect upon the health or safety of the general public.

Corrective Action:

The instruments were calibrated per Surveillance Procedure SP-158, and an engineering investigation has been requested to determine and resolve a possible design problem with the Meteorological Monitoring Tower.

Failure Data:

This is the fifth occurrence for the 175' wind direction. This is the fourth occurrence for the 175' temperature and 33' wind direction channel and the third occurrence for the 33' temperature channel. This is the nineteenth event reported under this Specification.