

CONTROL BLOCK: 

							(1)
--	--	--	--	--	--	--	-----

0	1	G	A	E	I	H	I	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	9	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58

0	1	REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE									
7	8	L	6	U	5	0	0	0	3	2	1	7	0	2	0	2	8	2	8	0	2	1	6	8	2	9															
		60	61	DOCKET NUMBER										68	69	EVENT DATE										74	75	REPORT DATE										80			

0 2 With the unit in refuel and while performing HNP-1-3001, High Reactor  
0 3 Pressure Instrument Functional Test and Calibration, 1B21-N023C, was  
0 4 found to actuate at 1085 psig. Tech Specs 3.2-1, Item 4, requires actu-  
0 5 ation at  $\leq 1045$  psig +14.25 head correction. The redundant instruments  
0 6 were operable. Plant operation nor the health and safety of the public  
0 7 was not affected by this event. This is a repetitive event as last re-  
0 8 ported on Reportable Occurrence Report No. 50-321/1981-115.

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE					
I A		E		E		I N S T R U				S		Z							
82		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE				REPORT TYPE		REVISION NO.							
82		004		03				L		0									
LER/RO REPORT NUMBER		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
E Z		Z		Z		0000		Y		N		N		B069					

1 0 | The cause of this event has been attributed to setpoint drift. The

1 1 | instrument, a Barksdale Model B2T, was calibrated per HNP-1-3001

1 2 | and returned to service.

1	3	
1	4	

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (28) H % POWER (29) 0 0 0 OTHER STATUS (30) NA METHOD OF DISCOVERY (31) B DISCOVERY DESCRIPTION (32) Surveillance Testing

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 7 8 9 10 11

2 3 4 5 6 7 8 9 10 11 12

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION
1	7	0	0	NA

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

6		9		11		12		80	
		LOSS OF OR DAMAGE TO FACILITY							
		TYPE		DESCRIPTION		(43)			
1	9	Z	(42)	NA					

8203080566 820216  
 PDR ADOCK 05000321  
 S PDR NA

2 0  
 7 8 9 10 68 69 80

NRC USE ONLY

PHONE: 912-367-7781

NRC USE ONLY

917-926

LER No.: 50-321/1982-004  
Licensee: Georgia Power Company  
Facility: Edwin I. Hatch  
Docket No.: 50-321

Narrative Report  
for LER 50-321/1982-004.

On February 2, 1982, with the unit in refuel and while performing HNP-1-3001, High Reactor Pressure Instrument Functional Test and Calibration, 1B21-N023C was found to actuate at 1085 psig. Tech Specs 3.2-1, Item 4, requires actuation at  $\leq 1045$  psig +14.25 head correction. The redundant instruments were operable. Plant operation nor the health and safety of the public was not affected by this event. This is a repetitive event as last reported on Reportable Occurrence Report No. 50-321/1981-115.

The cause of this event has been attributed to setpoint drift. The instrument, a Barksdale Model B2T, was calibrated per HNP-1-3001 and returned to service.