

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

5	1	A	L	J	M	F	2	2	0	0	-	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4			5
LICENSEE CODE								LICENSE NUMBER												LICENSE TYPE								CAT 58	
REPORT SOURCE		DOCKET NUMBER												EVENT DATE								REPORT DATE							

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2	At 1314 on 1/28/82, while re-aligning the swing CCW pump to the "A" train, the																																																																															
0	3	miscellaneous header was misaligned thereby cross connecting the two CCW loops																																																																															
0	4	(i.e. loops were no longer independent). Tech. Spec. 3.7.3 requires at least two																																																																															
0	5	independent component cooling water loops to be operable. Tech. Spec. 3.7.3 action																																																																															
0	6	statement requirements were met. Health/Safety of the public was not affected.																																																																															
0	7																																																																																
0	8																																																																																

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP SUBCODE		VALVE SUBCODE	
W	B	A	A	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z		
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
8	2	0	0	6	0	3	L	0							
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
H	Z	Z	Z	0	0	0	0	N	N	Z	Z	9	9	9	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	This event was caused by the failure to properly perform FNP-2-SOP-23.0 (Component																																																																															
1	1	Cooling Water System). Immediate action was taken to correct valve misalignment.																																																																															
1	2	Following the performance of FNP-2-STP-23.7 (CCW System Flow Path Verification Test),																																																																															
1	3	the CCW System was returned to service at 1443 on 1/28/82. Personnel involved have																																																																															
1	4	been counselled concerning this incident.																																																																															

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
E	0	9	9	NA	A	Operator Observation			
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
Z	Z	NA	NA						
PERSONNEL EXPOSURES		TYPE		DESCRIPTION					
0	0	Z	NA						
PERSONNEL INJURIES		TYPE		DESCRIPTION					
0	0	0	NA						
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
Z		NA							

8203080576 820226
PDR ADOCK 05000348
PDR

NRC USE ONLY

NAME OF PREPARER W. G. Hairston, III

PHONE (205) 899-5156