

LICENSEE EVENT REPORT

Attachment to AEEM-83/0292

Page 1 of 2

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M S G G S 1										2	0	0	-	0	0	0	C	-	0	0	3	4	1	1	1	1	4	5									
7	8	LICENSEE CODE										14	15	LICENSE NUMBER										25	26	LICENSE TYPE										30	57	CAT	58

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	4	1	6	7	0	1	0	7	8	3	8	0	5	1	8	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 On 1/7/83, an electrician preparing to route cable as required by a
0 3 maintenance work authorization noticed that the two wall penetrations
0 4 involved (Aux. Bldg. to Turbine Bldg.) had been previously opened. The
0 5 Control Room had not been notified prior to the work, therefore, no fire-
0 6 watch was in effect as required by T.S.3.7.7.a. The event had no effect
0 7 on the health and safety of the public and did not constitute a threat
0 8 to plant safety. This is reported pursuant to T.S.6.9.1.12.b.

09		SYSTEM CODE AB		11	CAUSE CODE A		12	CAUSE SUBCODE C		13	COMPONENT CODE ZZZZ				14	COMP. SUBCODE Z		15	VALVE SUBCODE Z		16					
17		LER RO REPORT NUMBER 83		21	EVENT YEAR 83		22	SEQUENTIAL REPORT NO. 001		23	OCCURRENCE CODE 01		24	REPORT TYPE X		25	REVISION NO. 1		26							
ACTION TAKEN H		18	FUTURE ACTION Z		19	EFFECT ON PLANT Z		20	SHUTDOWN METHOD Z		21	HOURS 0000		22	ATTACHMENT SUBMITTED Y		23	NPRD-4 FORM SUB. N		24	PRIME COMP. SUPPLIER Z		25	COMPONENT MANUFACTURER Z999		26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The event was due to personnel error in not giving prior notification
1 1 to the Control Room. An hourly fire watch was established upon
1 2 notification. Personnel were reinstructed on compliance to T.S.3.7.7 and
1 3 the requirement of giving prior notification to the Control Room. The
1 4 penetrations will be restored upon completion of the work authorization.

FACILITY STATUS (1) 5 (8) 28
 % POWER (10) 0 (11) 0 (12) 0 (29) NA
 OTHER STATUS (30)
 METHOD OF DISCOVERY (45) A (31) Observation During Job
 DISCOVERY DESCRIPTION (32)
 ACTIVITY CONTENT
 RELEASED OF RELEASE (1) 6 (8) 1 (9) 33 (10) 1 (11) NA
 AMOUNT OF ACTIVITY (35)
 LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	37	2	38	NA	39

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	0	0	0
2	0	0	0
3	0	0	0
4	0	0	0
5	0	0	0
6	0	0	0
7	0	0	0
8	0	0	0
9	0	0	0
10	0	0	0
11	0	0	0
12	0	0	0
13	0	0	0
14	0	0	0
15	0	0	0
16	0	0	0
17	0	0	0
18	0	0	0
19	0	0	0
20	0	0	0
21	0	0	0
22	0	0	0
23	0	0	0
24	0	0	0
25	0	0	0
26	0	0	0
27	0	0	0
28	0	0	0
29	0	0	0
30	0	0	0
31	0	0	0
32	0	0	0
33	0	0	0
34	0	0	0
35	0	0	0
36	0	0	0
37	0	0	0
38	0	0	0
39	0	0	0
40	0	0	0
41	0	0	0
42	0	0	0
43	0	0	0
44	0	0	0
45	0	0	0
46	0	0	0
47	0	0	0
48	0	0	0
49	0	0	0
50	0	0	0
51	0	0	0
52	0	0	0
53	0	0	0
54	0	0	0
55	0	0	0
56	0	0	0
57	0	0	0
58	0	0	0
59	0	0	0
60	0	0	0
61	0	0	0
62	0	0	0
63	0	0	0
64	0	0	0
65	0	0	0
66	0	0	0
67	0	0	0
68	0	0	0
69	0	0	0
70	0	0	0
71	0	0	0
72	0	0	0
73	0	0	0
74	0	0	0
75	0	0	0
76	0	0	0
77	0	0	0
78	0	0	0
79	0	0	0
80	0	0	0
81	0	0	0
82	0	0	0
83	0	0	0
84	0	0	0
85	0	0	0
86	0	0	0
87	0	0	0
88	0	0	0
89	0	0	0
90	0	0	0
91	0	0	0
92	0	0	0
93	0	0	0
94	0	0	0
95	0	0	0
96	0	0	0
97	0	0	0
98	0	0	0
99	0	0	0
100	0	0	0

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE: DESCRIPTION
1 9 2 (42) NA
7 8 9 10 8305250578 000510

PUBLICITY
 ISSUED (2) (1) N (44) NA (45)
 DESCRIPTION
 PDR ADCK 05000416
 S PDR
 NRC USE ONLY

NAME OF PREPARER Ron Byrd

PHONE

SUPPLEMENTARY INFORMATION TO
LER 83-001/01 X-1

Mississippi Power & Light Company
Grand Gulf Nuclear Station - Unit 1
Docket No. 50-416

Technical Specification Involved: 3.7.7.a
Reported Under Technical Specification: 6.9.1.12.b

Event Narrative:

This is an update to a previous report submitted on January 21, 1983. The following paragraphs describe the event.

An electrician preparing to route cable as required by a maintenance work authorization noticed that the two wall penetrations involved had already been opened. The penetrations were AE-257D and AE-258D (elevation 166 feet, Auxiliary Building to Turbine Building). He reported this to the Control Room. An LCO was entered and an hourly fire watch was established in accordance with Technical Specification 3.7.7.a.

It was not determinable exactly when the penetration was opened as the Control Room had not been notified prior to the activity. Maintenance work had been performed on these penetrations in September, but the penetrations were resealed by October 13, 1982.

Field engineers and work planners were made aware of the problem of opening penetrations without prior notification to the Control Room as corrective action to LER 82-132/01 T-0. These penetrations were likely opened prior to the reinstruction of personnel in December, 1982.

The penetrations will be restored upon completion of the work authorization. The authorization is part of a design change package which makes modification to the plant communications system. Estimated restoration date is June 15, 1983.

Previous Similar Event

LER 82-077/01 T-0
LER 82-132/01 T-0
LER 82-027/99 X-1
LER 82-031/99 X-1



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

May 18, 1983

JAMES P. McGAUGHY, JR.
VICE PRESIDENT

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 2900
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Update Report - Wall
Penetrations Found Open
With No Fire Watch
Established
LER 83-001/01 X-1
AECM-83/0292

This is an update to a previous report submitted on January 21, 1983. The event for which the report was submitted occurred on January 7, 1983, when an electrician preparing to route cable through two wall penetrations noticed they were already open. This was reported to the Control Room. An Limiting Condition for Operation was entered and an hourly fire watch was established in accordance with Technical Specification 3.7.7.a. The event was reported pursuant to Technical Specification 6.9.1.12.b.

The penetrations will be restored upon completion of the work authorization. Estimated restoration date is June 15, 1983. Attached is LER 83-001/01 X-1, with supplementary information.

Yours truly,

J. P. McGaughy
for J. P. McGaughy

JPM:sap
Attachment

cc: (See Next Page)

OFFICIAL COPY

IE 22

MISSISSIPPI POWER & LIGHT COMPANY

AECM-83/0292

Page 2

cc: Mr. J. B. Richard (w/a)
Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555