

## (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK:

0	1	M	D	C	C	N	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT		58

REPORT  
SOURCE

0 1  
7 8

REPORT SOURCE L 6 0 5 0 0 0 3 1 7 7 0 3 2 1 8 2 8 0 4 1 6 8 2 9  
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 0431 while performing a routine surveillance test, Control Element  
0 3 | Assembly (CEA) #21 dropped into the core. Power was reduced to 70% at  
0 4 | 0519 in accordance with T.S. 3.1.3.1 until the CEA was withdrawn and  
0 5 | aligned with the remainder of Group 2 CEAs at 0535. All other CEAs  
0 6 | remained operable during the event. LERs 50-318/81-99 and  
0 7 | 50-317/81-39 describe similar events.  
0 8 |

09		SYSTEM CODE R B		11	CAUSE CODE X		12	CAUSE SUBCODE X		13	COMPONENT CODE X X X X X X					14	COMP. SUBCODE Z		15	VALVE SUBCODE Z		16
7	8	9	10		11		12								18		19			20		
17		LER/RO REPORT NUMBER		EVENT YEAR 8 2		21	22	SEQUENTIAL REPORT NO. 0 1 1		24	25	26	OCCURRENCE CODE 0 3		28	29	REPORT TYPE L		30	REVISION NO. 0		32
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		22	ATTACHMENT SUBMITTED		23	NPRD-4 FORM SUB.		24	PRIME COMP. SUPPLIER		25	COMPONENT MANUFACTURER		26
Z		G		B		Z		0 0 0 1			Y			N			N			Z 9 9 9		
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | An electrical test of the CEA during its operation disclosed no cause  
1 1 | for the event. Results of the test have been forwarded to the NSSS sup-  
1 2 | plier. Further investigation will be conducted during the upcoming re-  
1 3 | fueling outage. In addition, the monthly surveillance test procedure is  
1 4 | being revised.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
1	5	E	28	1	0	0	29	NA	B	31	Surveillance Test	32
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE						
1	6	Z	33	Z	34	NA	35	NA	36			
PERSONNEL EXPOSURES		TYPE		DESCRIPTION								
1	7	0	0	0	37	Z	38	NA	39			
PERSONNEL INJURIES		DESCRIPTION										
1	8	0	0	0	40	NA	41					
LOSS OF OR DAMAGE TO FACILITY		DESCRIPTION										
1	9	Z	42	NA	43							
PUBLICITY		ISSUED		DESCRIPTION								
2	0	N	44	8204270170	45	NA						

NAME OF PREPARER M. A. Junge/J. W. Raynor

PHONE 301-269-4969/4713

LER NO. 82-II/3L  
DOCKET NO. 50-317  
LICENSE NO. DPR-53  
EVENT DATE 03-21-82  
REPORT DATE 04-16-82  
ATTACHMENT

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

An electrical test of the CEA during its operation disclosed no cause for this event. The results of this test were forwarded to the NSSS supplier, who concurred with the licensee's analysis, but has suggested changes to the lift coil current settings. An investigation into these suggestions will be made during the upcoming refueling outage. If, after the investigation, any corrective action is deemed necessary, such action will be reported in an updated submittal of this report. Maintenance request #0-82-1237 will remain open for recording further maintenance action. In addition, the monthly surveillance test procedure is being revised to include pertinent NSSS supplier recommendations for the conduct of the surveillance test.