

LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			6														
7	8	9	LICENSEE CODE					14	15	LICENSE NUMBER										25	26	LICENSE TYPE					34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50

CON'T

REPORT SOURCE 0 1 7 8 L 6 0 5 0 0 0 2 2 0 7 0 4 1 9 8 3 8 0 5 1 7 8 3 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During a major maintenance outage while performing environmental surveillance
0 3 | testing, the 30 foot wind direction sensor azimuth alignment was found to be mis-
0 4 | aligned by 9.8 degrees, which is in violation of the Environmental Technical Speci-
0 5 | fication 3.1 in which the wind sensor is required to be calibrated for an accuracy
0 6 | of ± 5 degrees. Similar events were reported in LER 83-01 and 83-08.
0 7 |
0 8 |
7 8 9

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
		Z	Z	B	C	I	N	S	T	R	U	E	Z		
LER RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38
8	3			0	0	7		0	3	L		0			
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER	
39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54
E	Z	Z	Z	Z	Z			0	0	0	0	Y	N	X	T

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | This error is attributed to improper alignment of mounting plates when installed
1 1 | (in August 1982 during an equipment upgrade and readjusted in January 1983). Sub-
1 2 | sequently survey data used for alignment was found to be in error. The sensors have
1 3 | been readjusted, checked and found to be in compliance with the Technical Speci-
1 4 | fications.

1 5 [G] (28) % POWER 0 0 0 0 (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (B) (31) DISCOVERY DESCRIPTION (32) Technician Observation

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)
1 6 2 33 2 34 NA
LOCATION OF RELEASE (36)
NA

PERSONNEL EXPOSURES		TYPE		DESCRIPTION
NUMBER				
1	7	0	0	0
		(37)	Z	(38)
				NA

PERSONNEL INJURIES	
NUMBER	DESCRIPTION
180040	NA

7		8		9		11		12		80	
LOSS OF OR DAMAGE TO FACILITY										(43)	
TYPE										DESCRIPTION	
1	9	Z	(42)	NA							

7 8 9 10
 PUBLICITY
 ISSUED DESCRIPTION (45)
 (2) (0) (N) (44)
 8305270075 830517
 PDR ADOCK 05000220
 S PDR
 NRC USE ONLY

8305270075 830517
PDR ADCK 05000220
S PDR

NRC USE ONLY

NAME OF PREPARER Anthony Iavenditti

PHONE (315) 349-2611

LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N Y N M P 1 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4

LICENSEE CODE

LICENSE NUMBER

LICENSE TYPE

CONT

0 1 L 6 0 5 0 0 0 2 2 0 7 0 4 1 9 8 3 8 0 5 1 7 8 3 9

REPORT
SOURCE

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During a major maintenance outage while performing Environmental Surveillance

0 3 Testing, the 200 foot wind direction sensor azimuth alignment was found to be

0 4 misaligned by 8.6 degrees, which is in violation of the Environmental Technical

0 5 Specification 3.1 in which the wind sensor is required to be calibrated for an

0 6 accuracy of ± 5 degrees. Similar events were reported in LER 83-01 and 83-07.

0 7

0 8

0 9 Z Z 11 B 12 C 13 I N S T R U 14 E 15 Z 16

17 LER-RO REPORT NUMBER 8 3 0 0 8 0 3 L 0

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

E 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 X 25 T 1 0 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 This error is attributed to improper alignment of mounting plates when installed

1 1 (in August 1982 during an equipment upgrade). Subsequently, survey data used for

1 2 alignment was found to be in error. The sensors have been readjusted, checked

1 3 and found to be in compliance with the Technical Specifications.

1 4

1 5 G 28 0 0 0 29 NA 30 31 B 32 Technician Observation

1 6 Z 33 Z 34 NA 35 NA 36 NA

1 7 0 0 0 37 Z 38 NA 39

1 8 0 0 0 40 NA 41

1 9 Z 42 NA 43

2 0 N 44 NA 45

NAME OF PREPARER Anthony Iavenditti

PHONE (315) 349-2611

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

May 19, 1983

Mr. James M. Allan
Acting Regional Administrator
United States Nuclear Regulatory Comm.
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

RE: Docket No. 50-220
LER 83-07, 83-08


Dear Mr. Allan

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specifications, we hereby submit the following licensee event reports:

83-07, 83-08 which are being submitted in accordance with Environmental Technical Specification 3.1, the Meteorological Monitoring System shall measure parameters as prescribed by Table 3.1-1 to provide data that is representative of atmospheric conditions that exist at all gaseous effluent release points.

This report was completed in the format designated in NUREG-0262, dated July 1977.

Very truly yours



Charles V. Mangan
Vice President
Nuclear Engineering & Licensing

CVM/RGR/jm

Attachments (3 copies)

cc: Director, Office of I&E (30 copies)
Director, Office of MIPC (3 copies)

I E22
11