

CONTROL BLOCK:

--	--	--	--	--	--

 ①

0	1	N	J	S	G	S	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	LICENSEE CODE							14	LICENSE NUMBER											25	26	LICENSE TYPE				30	57	CAT	58

0 1
7 8

REPORT SOURCE L 6 0 5 0 0 0 2 7 2 7 0 4 0 3 8 2 8 0 4 1 3 8 2 9
6C 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

0 2 At 2330 hours, April 3, 1982, while performing a visual inspection of the Containment

Building, an operator discovered a service water leak on the flange of Valve 14SW65.

10 The leak rate was determined to be 0.5 GPM. In accordance with NRC IE Bulletin

80-24, the NRC was notified of the service water leak in containment by telephone,

06 | with written confirmation transmitted on April 5, 1982.

0	7	
---	---	--

08 _____ 8

0 9
 W A 11
 E 12
 B 13
 V A L V E X 14
 B 15
 D 16

(17) LER RO REPORT NUMBER

EVENT YEAR			SEQUENTIAL REPORT NO.				CODE			TYPE		NO.
8	2	-	0	1	8	/	0	1	T	-	0	
21	22	23	24	25	26	27	28	29	30	31	32	

ACTION TAKEN (D) (18) FUTURE ACTION (Z) (19) EFFECT ON PLANT (Z) (20) SHUTDOWN METHOD (Z) (21) HOURS (0) (0) (0) (0) (22) ATTACHMENT SUBMITTED (Y) (23) NPRD-4 FORM SUB. (N) (24) PRIME COMP. SUPPLIER (N) (25) COMPONENT MANUFACTURER (M) (1) (2) (0) (26)

1	0	The cause of the leakage was loose studs on the valve flange. The studs on the
---	---	--

11 | valve flange were torqued and the leakage stopped. At 0522 hours, March 4, 1982.

1 2 | the portion of the service water system involved was returned to service.

1 3

1	4
---	---

1 5 G 28 0 0 0 29 N/A 30 C 31 Non-routine Inspection 32

ACTIVITY CONTENT
RELEASED OF RELEASE

1	6	Z	33	Z	34
---	---	---	----	---	----

AMOUNT OF ACTIVITY (35)
N/A

LOCATION OF RELEASE (36)
N/A

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION	(39)				
1	7	0	0	0	(37)	Z	(38)	N/A	

PERSONNEL INJURIES	
NUMBER	DESCRIPTION
41	

[illegible]

1 9 Z (42) N/A
7 8 9 10
PUBICITY (45) NRC USE ONLY

ISSUED		DESCRIPTION	
2	0	N	N/A

NAME OF PREPARER R. Frahm

PHONE: 609-935-0998

8204270367