

## LICENSEE EVENT REPORT

CONTROL BLOCK: 

--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	J	S	G	S	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5																
7	8	9							14										25										26					30					37					58	
		LICENSEE CODE							LICENSE NUMBER															LICENSE TYPE																					

CON'T

REPORT SOURCE: 0 1 7 8  
DOCKET NUMBER: L 6 0 5 0 0 0 2 7 2 7 0 3 1 6 8 2 8 0 4 0 7 8 2 9  
EVENT DATE: 60 61 68 69 74 75  
REPORT DATE: 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On March 16, 1982 No. 1A Vital Bus tripped resulting in a loss of Component Cooling Water (CCW) and Service Water (SW) flows; the redundant CCW and SW pumps were tagged out for maintenance. All charging pumps, boron injection flow paths, Residual Heat Removal (RHR) loops and diesel generators were declared inoperable due to no CCW or SW flow. At 1055 hours Action Statements 3.1.2.1, 3.1.2.3, 3.4.1.4, 3.8.1.2 and 3.8.2.2 were entered.

0	8	
7	8	9

SYSTEM CODE      CAUSE CODE      CAUSE SUBCODE      COMPONENT CODE      COMP. SUBCODE      VALVE SUBCODE

E	B	(11)	R	E	L	A	Y	X	(14)	E	(15)	Z	(16)
9	10		11		12		13	18		19		20	

17 LER RO  
REPORT  
NUMBER

EVENT YEAR  
8 2

22

SEQUENTIAL  
REPORT NO.  
015

22

OCCURRENCE  
CODE

0	3
---	---

28 29

REPORT  
TYPE  
[L]  
30

31

REVISION  
NC.  
0  
32

ACTION TAKEN	FUTURE ACTION
A	Z

EFFECT  
ON PLANT

  Z   (2)

25

SHUTDOWN  
METHOD  
L Z (2)

HOURS 22

0 0 0 0

37 40

ATTACHMENT  
SUBMITTED  
Y 23  
41

NPRD-4  
FORM SUB.  
N 2  
42

PRIME COMP.  
SUPPLIER  
L 2  
43

COMPONENT  
MANUFACTURER

W	1	2	0
---	---	---	---

44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | A wire to the TD5 undervoltage relay had shorted to the feeder cubicle door, causing  
1 1 | the 1A Vital Bus infeed breaker to trip without automatic transfer. CCW and SW flows  
1 2 | were restored. All charging pumps, a boron injection flow path, both RHR loops and  
1 3 | all diesels were declared operable; one RHR loop was placed in operation. By 1140  
1 4 | hours, Action Statements 3.1.2.1, 3.1.2.3, 3.4.1.4, 3.8.1.2 and 3.8.22 had been  
7 8 9 terminated.

terminated.

FACILITY STATUS (28) 1 5 G 0 0 0 29 N/A 30 OTHER STATUS

METHOD OF DISCOVERY (31) A 32 DISCOVERY DESCRIPTION

Operator Observation

ACTIVITY CONTENT (35) 1 6 Z 33 Z 34 N/A 44 AMOUNT OF ACTIVITY

LOCATION OF RELEASE (36) 45 N/A 80

PERSONNEL EXPOSURES		NUMBER		TYPE	DESCRIPTION
1	7	0	0	0	(37) Z (38) N/A (39)

PERSONNEL INJURIES	
NUMBER	DESCRIPTION
00040	N/A

7		8	9	11		12	13	
LOSS OF OR DAMAGE TO FACILITY				(43)				
TYPE		DESCRIPTION						
1	9	Z	(42)	N/A				

7		8	9	10														80	
				PUBLICITY	(45)														NRC USE ONLY
ISSUED		N		(44)	DESCRIPTION														
2		0			N/A														
3		0																68	
																		69	
																		80	

NRC USE ONLY

8204270397 NAME OF PREPARER R. Frahm PHONE: 609-935-0998

5 PO 917-926