

# LICENSEE EVENT REPORT

Unit 1

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 T N S N P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 14 15 25 26 30 37 CAT 55  
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T

01 REPORT SOURCE L 6 0 5 0 0 0 3 2 7 7 0 7 0 8 8 2 8 0 7 2 1 8 2 9  
2 8 60 61 68 69 74 75 80  
 DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 Unit 1 in mode 1 at 100% RTP. At 1325 (C), the 1B1-B control and auxiliary vent  
03 board tripped. Train 'B' room coolers for safety injection, centrifugal charging,  
04 residual heat removal, and containment spray pumps were inoperable. The 'B' trains  
05 of emergency core cooling heat trace, emergency gas treatment, and control building  
06 emergency ventilation systems were also inoperable. LCO 3.0.3 was entered due to  
07 the 'A' train containment spray pump room cooler out of service for surveillance  
08 testing. There was no effect on public health or safety. Previous occurrences--none  
7 8 9

09 SYSTEM CODE S 11 CAUSE CODE A 12 CAUSE SUBCODE E 13 COMPONENT CODE C K T B R K 14 COMP. SUBCODE X 15 VALVE SUBCODE Z 16  
7 8 9 10 11 12 13 18 19 20  
 LER/RO REPORT NUMBER 8 2 17 EVENT YEAR 8 2 21 22 SEQUENTIAL REPORT NO. 0 8 0 24 26 OCCURRENCE CODE 0 1 28 29 REPORT TYPE T 30 REVISION NO. 0 32  
 ACTION TAKEN A 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED Y 23 NPRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER X 9 9 9 44 47  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The vent board tripped due to failure of the control transformer to the control  
11 building emergency pressurization fan. Due to an improperly sized fuse installed in  
12 the transformer, the control transformer was shorted by a defective relay in the fan  
13 control circuit. The 1B1-B control and auxiliary vent board was returned to  
14 service at 1440 (C).  
7 8 9

15 FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator observation 32  
7 8 9 10 12 13 44 45 46 80  
16 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36  
7 8 9 10 11 44 45 80  
17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39  
7 8 9 11 12 13 80  
18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41  
7 8 9 11 12 80  
19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43  
7 8 9 10 80  
20 PURCITY ISSUED N 44 DESCRIPTION NA 45  
7 8 9 10

8208020083 820721  
PDR ADOCK 05000327  
S PDR

NRC USE ONLY

## LER SUPPLEMENTAL INFORMATION

SQRO-50-327/82080

Technical Specification Involved: 3.0.3., 3.6.2.1,  
3.5.2, 3.6.1.8,  
3.5.4.2, & 3.7.7

Reported Under Technical Specification: 6.9.1.12.b

Date of Occurrence: 07/08/82

Time of Occurrence: 1325 CDT

Identification and Description of Occurrence:

At 1320 (c), both chlorine detectors were declared inoperable when the drip rate was determined slow. LCO 3.3.3.6 requires the control room emergency ventilation system be initiated and maintained under the circumstances. At 1325, after initiation of the control room emergency ventilation system, the control transformer to the control building emergency pressurizer fan failed causing a trip of the 1B1-B control and auxiliary vent board. This resulted in loss of power to various equipment and required entry into several LCOs.

Equipment InoperableLCO

Train B safety injection pump room cooler	3.5.2
Train B centrifugal charging pump room cooler	3.5.2
Train B residual heat removal pump room cooler	3.5.2
Train B containment spray pump room cooler	3.6.2.1
Train B emergency core cooling system heat trace	3.5.4.2
Train B emergency gas treatment system	3.6.1.8
Train B control building emergency ventilation system	3.7.7

LCO 3.0.3 was entered due to the train 'A' containment spray pump room cooler also being out of service for performance of SI-668.1, ERCW Pipe Corrosion Monitoring Instruction.

Apparent Cause of Occurrence:

Due to an improperly sized fuse installed in the transformer, the control transformer to the control building emergency pressurizer fan was shorted by a defective relay (1B-271) in the fan control circuit. The transformer failure resulted in blowing a fuse in the normal feeder breaker to the 1B1-B control and auxiliary vent board.

Analysis of Occurrence:

Investigation of the chlorine detectors established that the detectors were not inoperable. Instructions require performance of SI-168, "Periodic Calibration of Control Room Air Intake Chlorine Detection System," or SI-240, "Functional Test of Control Room Air Intake Chlorine Detection System," to determine operability of the detectors when the drip rate is slow. The detectors were declared inoperable and action of 3.3.3.6 was taken before either test was performed. Performance of SI-240 at 1424 (C) on 07/08/82 established that the chlorine detectors were not inoperable. A replacement control transformer was installed on 07/12/82, but this transformer also shorted following energizing the fan. Investigation discovered

a defective relay (1B-271) in the fan control circuit. Further investigation revealed a 10 amp fuse was installed in the control transformer, but the drawing required only a 1 amp fuse. The defective relay was a result of normal ageing failure. Installation of an improperly sized fuse has been attributed to personnel error during construction installation for the first failed transformer. Since the 10 amp fuse did not fail, maintenance personnel did not refer to the drawing for required fuse size. This resulted in the second transformer failure.

Corrective Actions:

Train A containment spray pump room cooler was returned to service at 1338 (C) following completion of SI-668.1. Power was restored to the 1B1-B control and auxiliary vent board which returned all of the above listed equipment to service at 1440 (C) except for train B control building emergency ventilation system which was returned to service on 07/12/82 at 1558 (C) after replacement of the control tranformer.

A nameplate has been installed at the control transformer stating to use a 1 amp fuse. A spot check of other control transformers was performed to ensure all had the correct size fuses installed. A program has begun to check all fuses protecting safety related equipment against the controlled as constructed drawings to assure porper sizing of all fuses. Nameplates will also be installed along side each fuse box indicating the correct fuse size.

Operations personnel will have SI-168 or SI-240 performed prior to declaring the chlorine detectors inoperable for slow drip rate.

Failure Data:

None.