

## LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

0 1 M I D C C 2 2 0 0 - 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAP

CON'T

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

0 1 L 6 0 5 0 0 0 3 1 6 7 0 4 12 8 8 3 3 0 5 2 7 8 3 9

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 1 2 DURING NORMAL OPERATIONS, THE N-TRAIN BATTERY ROOM PYROALARM DETECTOR R-33A,

0 1 3 ALARMED RENDERING THE 633 AUX. BLDG. DETECTORS INOPERABLE. A FIRE WATCH WAS POSTED

0 1 4 IMMEDIATELY UPON DISCOVERY. THIS CONDITION REMOVED ANY FURTHER CAPABILITY FOR THE

0 1 5 FIRE DETECTION SYSTEM TO ALARM IN THE CONTROL ROOM IF ANY ADDITIONAL PYROALARMS

0 1 6 WITHIN THE ZONE ALARMED. THIS EVENT WAS NONCONSERVATIVE WITH RESPECT TO T.S.

0 1 7 3.3.3.8. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED. PREVIOUS OCCURENCES:

0 1 8 RO 50-315/82-096, 83-034, AND RO 50-316/83-019.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

3 3 A B 11 E 12 Z 13 I N S T R U 14 E 15 Z 16

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

8 3 0 4 6 0 3 L 0

LEA/RQ REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

13 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

A Z Z Z 0 0 0 0 N N A P 4 3 5 25

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 1 1 RAIN LEAKING THROUGH THE ROOF SHORTED OUT THE DETECTOR, THUS CAUSING THE ALARM. THE

1 1 2 PYROALARM TERMINAL BLOCK WAS REPLACED, THE SYSTEM WAS VERIFIED OPERABLE AND RETURNED

1 1 3 TO SERVICE IN 4 HOURS AND 57 MINUTES. THE ROOF HAS BEEN REPAIRED TO PREVENT FURTHER

1 1 4 LEAKAGE.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

1 5 E 28 1 0 0 29 NA 30 A 31 OPERATOR OBSERVATION 32

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

1 6 Z 33 Z 34 NA 35 NA 36

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

1 7 0 0 0 37 Z 38 NA 39

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

1 8 0 0 0 40 NA 41

PERSONNEL INJURIES NUMBER DESCRIPTION

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

1 9 Z 42 NA 43

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

2 3 N 44 NA 45

PUBLICITY ISSUED DESCRIPTION

8306060273 830527  
PDR ADOCK 05000316  
S PDR

NRC USE ONLY

NAME OF PREPAPER PAUL CARTEAUX

PHONE 616-465-5901