

Unit 2

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'TEVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	8
---	---

17 LER/RO
REPORT
NUMBER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

PUBLICITY
 ISSUED DESCRIPTION (45)
 0 N (44) NA
 8306070218 830601
 PDR ADDCK 05000328
 S PDR
 NRC USE ONLY

Phone: (615) 870-6422

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
1750 Chestnut Street Tower II

June 1, 1983

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street, NW
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 2 - DOCKET
NO. 50-328 - FACILITY OPERATING LICENSE DPR-79 - REPORTABLE OCCURRENCE
REPORT SQRO-50-328/83068

The enclosed report provides details concerning the low level in the
refueling water storage tank (RWST) caused by overfilling the No. 2 cold
leg accumulator. This report is submitted in accordance with Sequoyah
unit 2 Technical Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



H. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Inspector, Sequoyah

OFFICIAL COPY

IE 22
111