

LICENSEE EVENT REPORT

Attachment to AECM-82/462

Page 1 of 1

CONTROL BLOCK:

| | | | | | | | |
|--|--|--|--|--|--|--|-----|
| | | | | | | | (1) |
|--|--|--|--|--|--|--|-----|

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|---|---------------|---|---|---|---|---|----|----------------|---|---|---|---|---|---|---|---|---|----|--------------|---|---|---|---|----|-----|--|----|---|
| 0 | 1 | M | S | G | G | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | | | 5 |
| 7 | 8 | LICENSEE CODE | | | | | | 14 | LICENSE NUMBER | | | | | | | | | | 25 | LICENSE TYPE | | | | | 30 | CAT | | 58 | |

CON'T

7 8 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | Smoke detectors in the fuel handling area and main steam tunnel alarmed and would
0 3 | not clear. Investigation by operations personnel revealed no smoke or fumes. The
0 4 | alarms were deactivated and declared inoperable. A fire watch was established per
0 5 | Tech Spec 3.3.7.9. There was no effect on the health and safety of the public. This
0 6 | event did not constitute a threat to plant safety.
0 7 |
0 8 |
7 8 9 80

| | | | | | | | | | | | | | | | | |
|----------------------|---|----------------------|----|------------------------|----|-----------------|----|----------------|---|----------------------|---|---|---------------|--|---------------|--|
| 09 | | SYSTEM CODE | | CAUSE CODE | | CAUSE SUBCODE | | COMPONENT CODE | | | | | COMP. SUBCODE | | VALVE SUBCODE | |
| 7 | 8 | A | B | C | Z | I | N | S | T | R | U | E | Z | | | |
| | | 11 | 12 | 13 | 14 | 15 | 16 | | | | | | | | | |
| 17 | | EVENT YEAR | | SEQUENTIAL REPORT NO. | | OCCURRENCE CODE | | REPORT TYPE | | REVISION NO. | | | | | | |
| LER/RO REPORT NUMBER | | 82 | | 065 | | 03 | | L | | 0 | | | | | | |
| 21 | | 22 | | 23 | | 24 | | 25 | | 26 | | | | | | |
| ACTION TAKEN | | FUTURE ACTION | | EFFECT ON PLANT | | SHUTDOWN METHOD | | HOURS | | ATTACHMENT SUBMITTED | | | | | | |
| X | | Z | | Z | | Z | | 0000 | | N | | | | | | |
| 18 | | 19 | | 20 | | 21 | | 22 | | 23 | | | | | | |
| 33 | | 34 | | 35 | | 36 | | 37 | | 40 | | | | | | |
| NPRD-4 FORM SUB. | | PRIME COMP. SUPPLIER | | COMPONENT MANUFACTURER | | | | | | | | | | | | |
| N | | A | | H260 | | | | | | | | | | | | |
| 24 | | 25 | | 26 | | | | | | | | | | | | |
| 42 | | 43 | | 44 | | | | | | | | | | | | |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The continuous alarm was caused by dust accumulation on the ionization smoke detector.

1 1 The detectors were cleaned and placed back into service on 14 Sept 82. This is

1 2 intended to be a final report.

1 3

1 4

FACILITY STATUS (1) 5 (B) (28) % POWER (0) (0) (0) (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (A) (31) Alarmed Condition DISCOVERY DESCRIPTION (32)
 ACTIVITY CONTENT RELEASED OF RELEASE (1) 6 (Z) (33) (Z) (34) AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36)
 PERSONNEL EXPOSURES NUMBER (1) 7 (0) (0) (0) (37) TYPE (Z) (38) DESCRIPTION (39) NA
 PERSONNEL INJURIES NUMBER (1) 8 (0) (0) (0) (40) DESCRIPTION (41) NA
 LOSS OF OR DAMAGE TO FACILITY TYPE (1) 9 (Z) (42) DESCRIPTION (43) 8210080298 821005 PDR ADOCK 05000416 S PDR
 PUBLICITY ISSUED (2) 0 (N) (44) DESCRIPTION (45) NA NRC USE ONLY
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

NAME OF PREPARER Original signed by Ron Byrd

PHONE: _____