

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	1	2	0	0	-	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4	5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 9 14 15 25 26 30 57 CAT 58

CON'T

0	1	L	6	0	5	0	0	0	3	1	7	7	0	9	2	7	8	2	8	1	0	2	5	8	2	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 1640 while increasing power, pressurizer level deviated slightly from

0 3 | the program level by greater than +/-5% (T.S. 3.4.4). The pressurizer

0 4 | level controller was discovered to be in the local setpoint mode of

0 5 | operation. The controller was switched to remote setpoint and pres-

0 6 | surizer level returned to normal at 1647.

0 7 | Similar events: none.

0	9	C	B	11	A	12	A	13	Z	Z	Z	Z	Z	Z	14	Z	15	Z	16	17	8	2	—	0	6	2	—	0	3	L	—	0	18	Z	19	Z	20	Z	21	0	0	0	0	N	23	N	24	Z	25	Z	9	9	9	9	26
---	---	---	---	----	---	----	---	----	---	---	---	---	---	---	----	---	----	---	----	----	---	---	---	---	---	---	---	---	---	---	---	---	----	---	----	---	----	---	----	---	---	---	---	---	----	---	----	---	----	---	---	---	---	---	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | During instrumentation calibration, the pressurizer level controller was

1 1 | placed in the local setpoint mode of operation. Upon completion of cali-

1 2 | bration, the Control Room Operator inadvertantly left the controller in

1 3 | the local setpoint mode. A procedure change to ensure the controller is

1 4 | in the remote setpoint mode prior to entering Mode 2 has been completed.

1	5	C	28	0	5	5	29	N/A	A	31	Operator Observation	32
---	---	---	----	---	---	---	----	-----	---	----	----------------------	----

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NAME OF PREPARER M. A. Junge

PHONE 301-269-4969

NRC USE ONLY