




Commonwealth Edison
LaSalle County Nuclear Station
2601 N. 21st Road
Marseilles, Illinois 61341
Telephone 815/357-6761

August 3, 1994

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Licensee Event Report #94-010-00, Docket #050-373 is being submitted to your office in accordance with 10CFR50.73(a)(2)(iv).



D. J. Ray
Station Manager
LaSalle County Station

DJR/TJ/lja

Enclosure

cc: NRC Region III Administrator
NRC Senior Resident Inspector
INPO - Records Center
IDNS Resident Inspector
IDNS Senior Reactor Analyst
Nuclear Licensing Administrator

000000

9408100149 940803
PDR ADDCK 05000373
S PDR

JE221

LICENSEE EVENT REPORT (LER)																		Form Rev 3.0								
Facility Name (1) LaSalle County Station Unit 1														Docket Number (2) 0 5 0 0 0 3 7 3				1 of 0 3								
Title (4) Scram Due to Reactor Water Level Control Signal Loss to the 1B Turbine Driven Reactor Feed Pump																										
Event Date (5)			LER Number (6)				Report Date (7)				Other Facilities Involved (8)															
Month	Day	Year	Year	///	Sequential	///	Revision	Month	Day	Year	Facility Names				Docket Number(s)											
				///	Number	///	Number																			
0	7	0	5	9	4	9	4	---	0	1	0	---	0	0	0	8	0	3	9	4						
OPERATING MODE (9)		1		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10CFR (Check one or more of the following) (11)																						
POWER LEVEL (10)	0		5		6		20.402(b)		20.405(c)		X		50.73(a)(2)(iv)		73.71(b)											
							20.405(a)(1)(i)		50.36(c)(1)				50.73(a)(2)(v)		73.71(c)											
							20.405(a)(1)(ii)		50.36(c)(2)				50.73(a)(2)(vii)		Other (Specify											
							20.405(a)(1)(iii)		50.73(a)(2)(i)				50.73(a)(2)(viii)(A)		in Abstract											
							20.405(a)(1)(iv)		50.73(a)(2)(ii)				50.73(a)(2)(viii)(B)		below and in											
						20.405(a)(1)(v)		50.73(a)(2)(iii)				50.73(a)(2)(x)		Text)												
LICENSEE CONTACT FOR THIS LER (12)																										
Name Jack Otley, System Engineer, Extension 2447														TELEPHONE NUMBER												
														AREA CODE												
														8 1 5		3 5 7 - 6 7 6 1										
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																										
CAUSE	SYSTEM	COMPONENT			MANUFAC- TURER			REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT			MANUFAC- TURER			REPORTABLE TO NPRDS									
X	S	J	C	B	D	B	0	4	0	Yes																
SUPPLEMENTAL REPORT EXPECTED (14)																		Expected Submission Date (15)	Month	Day	Year					
X YES (If yes, complete EXPECTED SUBMISSION DATE)																		NO	1	0	2	8	9	4		
ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)																										

At 0336 hours on July 5, 1994, Unit 1 scrambled from a power level of 601 MWe and 56.4% Core Thermal Power. The unit had been in Operational Condition 1 (Run) with the 1B Turbine Driven Reactor Feed Pump (TDRFP, FW)[SJ] in 3 element control and the Motor Driven Reactor Feed Pump in manual. The 1A TDRFP was unavailable pending additional post modification testing of the feedwater control system. Just prior to the scram, a loss of the Reactor Water Level Control signal caused the 1B TDRFP to ramp to minimum speed, resulting in a decrease in Reactor Vessel level. The reactor scrambled on a Reactor Low Water Level Scram (12.5 inches). The lowest reactor vessel level during the transient was -6 inches. Normal level was restored using the Motor Driven Reactor Feed Pump. Subsequent investigation determined the cause of the feedwater transient was due to a failure of the Manual Control Board Unit.

This event is being reported pursuant to 10CFR50.73(a)(2)(iv) as an event that resulted in automatic actuation of the Reactor Protection System.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION														Form Rev 3.0	
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)													
		Year	/// /// ///	Sequential Number	/// /// ///	Revision Number									
LaSalle County Station Unit 1	0 5 0 0 0 3 7 3	9	4	-	J	1	0	-	0	0	0	2	OF	0 3	
TEXT Energy Industry Identification System (EIIIS) codes are identified in the text as [XX]															

PLANT AND SYSTEM IDENTIFICATION

General Electric - Boiling Water Reactor

Energy Industry Identification System (EIIIS) codes are identified in the text as [XX].

A. CONDITION PRIOR TO EVENT

Unit(s): 1 Event Date: 7/05/94 Event Time: 0336 Hours
 Reactor Mode(s): 1 Modes(s) Name: Run Power Level(s): 56%

B. DESCRIPTION OF EVENT

Operators were pulling rods to increase power after Reactor Recirculation (RR)[AD] pump upshift. At 0336 hours with Unit 1 at 601 MWE and 56.4% Core Thermal Power the 1B Turbine Driven Reactor Feed Pump (TDRFP, FW)[SJ], while in 3 element control (Motor Driven Reactor Feed Pump in manual) lost a Reactor Water Level Control signal causing the 1B TDRFP to ramp to minimum flow. The Operator attempted, but was unable, to gain control of Reactor Vessel water level. The Reactor scrambled on 12.5 inch Low Reactor Water Level. Procedure LGP-3-2, "REACTOR SCRAM", was entered. The lowest Reactor Pressure Vessel (RPV) level was -6 inches. Procedure LGA-01, "RPV CONTROL" was entered and level was restored with the Motor Driven Reactor Feed Pump. The "A" Electro Hydraulic Control (EHC, EH)[TG] Pump also tripped following the 151 switchgear fast transfer.

This event is being reported pursuant to 10CFR50.73(a)(2)(iv) as an event that resulted in automatic actuation of the Reactor Protection System.

C. APPARENT CAUSE OF EVENT

The cause of the Reactor Low Water Level Scram was loss of feed flow to the Reactor Pressure Vessel (RPV) following the loss of control signal to the 1B TDRFP. The loss of this control signal resulted in ramping the 1B TDRFP output flow to zero and subsequently the Reactor Low Water Level Scram. Manual control of the 1B TDRFP did not respond due to the failed component. The cause of the 1B TDRFP control signal failure has been determined to be a Manual Control Board Unit (1C34-K653B) which provides the output signal from the Reactor Water Level Control (RWLC, LC)[BD] System to the 1B TDRFP Lovejoy Speed Control System. Both automatic and manual signals are processed through this card.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION												Form Rev 3.0			
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)													
		Year	///	Sequential Number	///	Revision Number									
LaSalle County Station Unit 1	0 5 0 0 0 3 7 3	9	4	-	0	1	0	-	0	0	0	3	OF	0	3

TEXT Energy Industry Identification System (EIIIS) codes are identified in the text as [XX]

D. SAFETY ANALYSIS OF EVENT

The safety consequences of this event were minimal. All Engineered Safety Feature (ESF) actuations occurred as designed on the Reactor Low Water Level Scram. Loss of total feedwater flow with the reactor at 104.8% power, analyzed as a moderate frequency transient in Section 15.2.7 of the Updated Final Safety Analysis Report (UFSAR), bounds this event.

E. CORRECTIVE ACTIONS

The 1C34-K653B circuit card was replaced. The failed circuit card is being tested by the manufacturer to determine failure cause. The results of the circuit card component testing will be reported in a supplemental report to this LER.

The 1A EHC Pump trip was found to be due to switchgear 131A breaker trip device having two leaking dash pots. These were repaired. Trip devices of this type used in safety related applications had previously been replaced with a more reliable device. The non-safety trip devices are currently undergoing evaluation for replacement with a more reliable device.

F. PREVIOUS EVENTS

The following scrams have occurred due to feedwater control:

<u>LER No.</u>	<u>Title</u>
373/91-006	Reactor Scram on Low Reactor Vessel Water Level Due to Loss of "A" Turbine Driven Reactor Feedwater Pump Caused by Control Valve Closure
373/93-011	Unit 1 - Manual Scram Due to Disconnected Linkage on Valve Positioner on a Heater Drain Valve

G. COMPONENT FAILURE DATA

<u>Manufacturer</u>	<u>Nomenclature</u>	<u>Model Number</u>	<u>MFG Part Number</u>
Bailey	Manual Control Board Unit	722	722001AAAA1