

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366 367 368 369 370 371 372 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387 388 389 390 391 392 393 394 395 396 397 398 399 400 401 402 403 404 405 406 407 408 409 410 411 412 413 414 415 416 417 418 419 420 421 422 423 424 425 426 427 428 429 430 431 432 433 434 435 436 437 438 439 440 441 442 443 444 445 446 447 448 449 450 451 452 453 454 455 456 457 458 459 460 461 462 463 464 465 466 46

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	7	8	A	9	R	10	A	11	I	12	N	13	O	14	2	12	0	15	0	16	0	17	0	18	0	19	0	20	0	21	0	22	0	23	0	24	0	25	4	26	1	27	1	28	1	29	1	30	1	31	4	32	1	33	1	34	5	35	7	36	CAT	37	58
			LICENSEE CODE												LICENSE NUMBER												LICENSE TYPE												CAT																								
01	7	8	REPORT SOURCE												16	60	0	61	1	62	5	63	0	64	0	65	0	66	0	67	3	68	6	69	8	70	1	71	1	72	2	73	4	74	8	75	2	76	1	77	1	78	2	79	1	80	3	81	8	82	2	83	19
			DOCKET NUMBER												EVENT DATE												REPORT DATE																																				

EVENT DESCRIPTION AND PROBABLY CONSEQUENCES 10

On 11/24/82 while in Mode 1 at 30% full power, a steam leak was discovered coming from a fitting on an emergency feedwater (EFW) pump steam supply pressure transmitter 2PT-0340. The isolation valve (2MS-0340) for the transmitter could not be closed at the time of the occurrence. The steam supply was isolated by closing the upstream control valves 2CV-1000 and 2CV-1050. This removed the steam driven EFW pump 2P-7A from service. EFW pump 2P-7B and associated train remained operable during this occurrence. After isolating the steam system, operations personnel were able to close the transmitter isolation valve so that repairs could be made with the EFW pump in service. The EFW pump 2P-7A was out of service for approximately 1 hour and 20 minutes.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP SUBCODE		VALVE SUBCODE		REVISION			
1 2 3 4 5 6 7 8		9 10 11 12		13 14 15 16 17 18		19 20 21 22 23 24		25 26 27 28 29 30		31 32 33 34 35 36		37 38 39 40 41 42		43 44 45 46 47 48			
LER/RO	EVENT YEAR	1 2 3 4 5 6 7 8		9 10 11 12 13 14 15 16		SEQUENTIAL REPORT NO.				OCCURRENCE CODE				REPORT TYPE		NO	
17 REPORT	1 2 3 4 5 6 7 8	9 10 11 12 13 14 15 16		17 18 19 20 21 22 23 24		25 26 27 28 29 30 31 32				33 34 35 36 37 38 39 40				41 42 43 44 45 46 47 48		49 50 51 52 53 54 55 56	
NUMBER	1 2 3 4 5 6 7 8	9 10 11 12 13 14 15 16		17 18 19 20 21 22 23 24		25 26 27 28 29 30 31 32				33 34 35 36 37 38 39 40				41 42 43 44 45 46 47 48		49 50 51 52 53 54 55 56	
ACTION	FUTURE	EFFECT		SHUTDOWN		ATTACHMENT				NPRD-4		PRIME COMP.		COMPONENT			
TAKEN	ACTION	ON PLANT		METHOD		SUBMITTED				FORM SUB		SUPPLIER		MANUFACTURER			
1 2 3 4 5 6 7 8	9 10 11 12 13 14 15 16	17 18 19 20 21 22 23 24		25 26 27 28 29 30 31 32		33 34 35 36 37 38 39 40				41 42 43 44 45 46 47 48		49 50 51 52 53 54 55 56		57 58 59 60 61 62 63 64			
33	34	35		36		37				38		39		40			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 | 0 | Valve 2MS-0340 was relocated as part of a design change. Apparently when the tubing connector was installed, it
1 | 1 | was overtorqued, thus causing the threads to strip. The tubing connector was replaced, and the transmitter was
1 | 2 | calibrated and returned to service.
1 | 3 |
1 | 4 |
7 | 8 |
9 |

FACILITY STATUS		% POWER	OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	10	13	10	129	1	NA	130
7	8	9	10	13	44	45	46	132
ACTIVITY RELEASED		CONTENT OF RELEASE	AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	12	134	1	NA	135	1	136
7	8	9	10	11	44	45	46	80

PERSONNEL EXPOSURES		DESCRIPTION
NUMBER	TYPE	
1010137	213B	NA
7	8	139

PERSONNEL INJURIES										80	
NUMBER					DESCRIPTION						
1	2	3	4	5	6	7	8	9	10	11	12
7	1	3	8	9	0	0	0	10	11	12	13
NA											141

LOSS OF OR DAMAGE TO FACILITY		80
TYPE	DESCRIPTION	
1 9	2 42 NA	43

PUBLICITY									
ISSUED		DESCRIPTION							
1	2	3	4	5	6	7	8	9	10
7	8	9	10	11	12	13	14	15	16
NRC USE ONLY									

NAME OF PREPARER Patrick Rogers

PHONE: (501) 964-3100

8212290223 821213
PDR ADOCK 05000368
S PDR

LICENSEE EVENT REPORT

EXHIBIT A

LER NO. 82-041/03L-0

Page 2

Occurrence Date: 11/24/82

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (continued)

This occurrence is reportable per Tech. Spec. 6.9.1.9.b. There have been no similar LER's.