

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 CIA DICPI 12 000-0 000000-000341111145
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 50

CONT
01 L 0510002750050983005231830
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 Prior to fuel load, while welding a reinforcement pad on a branch connec-
03 tion to the non-vital loop C component cooling water system, water began
04 leaking from the weld area. This event has in no way affected public
05 health and safety. Reportable per technical specification section
06 6.9.1.12.1.
07
08

09 WIB 11 A 12 E 13 PIPIEXIX 14 A 15 Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

17 813 18 0107 19 011 20 T 21 0
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

22 0000 23 Y 24 N 25 L 26 X191919
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 This is an "Interim Report". Basic cause of the leak was a flaw in the
11 root pass of the shop weld joining the branch connection to the main
12 header. Removal of the fillet overweld while preparing the weld area for
13 addition of the reinforcement pad provided a leakage path for the water.
14 Repairs will be made using an approved ASME section XI repair program.
15 B 16 Z 17 0 18 0 19 0 20 0 21 0 22 0 23 0 24 0 25 0 26 0 27 0 28 0 29 0 30 0 31 0 32 0 33 0 34 0 35 0 36 0 37 0 38 0 39 0 40 0 41 0 42 0 43 0 44 0 45 0 46 0 47 0 48 0 49 0 50 0 51 0 52 0 53 0 54 0 55 0 56 0 57 0 58 0 59 0 60 0
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
15 B 16 0000 17 N/A 18 A 19 During construction
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

20 Z 21 0 22 0 23 0 24 0 25 0 26 0 27 0 28 0 29 0 30 0 31 0 32 0 33 0 34 0 35 0 36 0 37 0 38 0 39 0 40 0 41 0 42 0 43 0 44 0 45 0 46 0 47 0 48 0 49 0 50 0 51 0 52 0 53 0 54 0 55 0 56 0 57 0 58 0 59 0 60 0
ACTIVITY RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
16 Z 17 0 18 0 19 0 20 0 21 0 22 0 23 0 24 0 25 0 26 0 27 0 28 0 29 0 30 0 31 0 32 0 33 0 34 0 35 0 36 0 37 0 38 0 39 0 40 0 41 0 42 0 43 0 44 0 45 0 46 0 47 0 48 0 49 0 50 0 51 0 52 0 53 0 54 0 55 0 56 0 57 0 58 0 59 0 60 0

PERSONNEL EXPOSURES
17 0 18 0 19 0 20 0 21 0 22 0 23 0 24 0 25 0 26 0 27 0 28 0 29 0 30 0 31 0 32 0 33 0 34 0 35 0 36 0 37 0 38 0 39 0 40 0 41 0 42 0 43 0 44 0 45 0 46 0 47 0 48 0 49 0 50 0 51 0 52 0 53 0 54 0 55 0 56 0 57 0 58 0 59 0 60 0
NUMBER TYPE DESCRIPTION

PERSONNEL INJURIES
18 0 19 0 20 0 21 0 22 0 23 0 24 0 25 0 26 0 27 0 28 0 29 0 30 0 31 0 32 0 33 0 34 0 35 0 36 0 37 0 38 0 39 0 40 0 41 0 42 0 43 0 44 0 45 0 46 0 47 0 48 0 49 0 50 0 51 0 52 0 53 0 54 0 55 0 56 0 57 0 58 0 59 0 60 0
NUMBER DESCRIPTION

LOSS OF OR DAMAGE TO FACILITY
19 Z 20 0 21 0 22 0 23 0 24 0 25 0 26 0 27 0 28 0 29 0 30 0 31 0 32 0 33 0 34 0 35 0 36 0 37 0 38 0 39 0 40 0 41 0 42 0 43 0 44 0 45 0 46 0 47 0 48 0 49 0 50 0 51 0 52 0 53 0 54 0 55 0 56 0 57 0 58 0 59 0 60 0
TYPE DESCRIPTION

PUBLICITY
20 Y 21 PGandE News Release on May 13, 1983
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
ISSUED DESCRIPTION

NAME OF PREPARER William J. Kelly PHONE 805/595-7351

ATTACHMENT TO LER 83-007/01T-0
PACIFIC GAS AND ELECTRIC COMPANY
DIABLO CANYON UNIT 1
DOCKET NO. 50-275

SUPPLEMENTAL INFORMATION

Ultrasonic examination and evaluation of ten similar welds without a reinforcement pad indicated the possibility that a full penetration shop weld was not made as required by Code. The affected portion of the component cooling water system was drained and the branch line connection removed for examination. A full penetration weld was present, with a small area (approximately 1/16 inch) where full penetration was not achieved at the weld root. Grinding on the weld surface in preparation for the installation of a reinforcing pad provided a leakage path for water. Repair to this weld will be made in accordance with an approved ASME Section XI repair program.

Presence of the full penetration weld in the CCW branch connection affects the credibility of the results of UT examination of the ten similar welds. Investigation into this matter will continue and results will be submitted in a revision to the LER.

PACIFIC GAS AND ELECTRIC COMPANY

PG&E

77 BEALE STREET • SAN FRANCISCO, CALIFORNIA 94106 • (415) 391-4111 TWX 910-372-6587

RECEIVED
NRC

1983 MAY 25 AM 11:02

REGION V I&E

JAMES D. SHIFFER
MANAGER

DEPARTMENT OF NUCLEAR PLANT OPERATIONS
NUCLEAR POWER GENERATION

May 23, 1983

Mr. John B. Martin, Regional Administrator
U.S. Nuclear Regulatory Commission, Region V
1450 Maria Lane, Suite 210
Walnut Creek, CA 94596-5368


Re: Docket No. 50-275, OL-DPR-76
Diablo Canyon Unit 1
Licensee Event Report 83-007/01T-0
Weld in Component Cooling Water System

Dear Mr. Martin:

Pursuant to Section 6.9.1.12.i of the Technical Specifications, Appendix A to the Diablo Canyon Unit 1 Operating License, the enclosed Licensee Event Report is submitted concerning a discrepancy in a shop weld in the Component Cooling Water System.

This event has in no way affected public health and safety.

Sincerely,



JDS:vk

Enclosure

cc w/enc: Mr. George W. Knighton, Chief
Licensing Branch No. 3
Division of Licensing
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director, Office of Management Information
and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Service List

IE-22
83-110