

Docket No. 50-346

License No. NPF-3

Serial No. 1-328

February 28, 1983



RICHARD P. CROUSE  
Vice President  
Nuclear  
(419) 259-5221

Richard C. DeYoung, Director  
Office of Inspection & Enforcement  
United States Nuclear Regulatory Commission  
Washington, D. C. 20555

Dear Mr. DeYoung:

On December 3, 1982 (Log No. 1-715), Toledo Edison received IE Bulletin 82-04: Deficiencies in Primary Containment Electrical Penetration Assemblies.

Toledo Edison has determined that no Bunker Ramo electrical penetration assemblies utilizing the hard epoxy module design are installed at Davis-Besse Nuclear Power Station, Unit No. 1. Also, Toledo Edison does not plan to install such assemblies in the future.

This completes the requested actions by Toledo Edison pertaining to IE Bulletin 82-04. If we can be of further assistance in this matter, please feel free to contact us.

Very truly yours,

*R P Crouse / Rm*

RPC:RFP:nlf  
cc: DB-1 NRC Resident Inspector

8303080047 830228  
PDR ADOCK 05000346  
PDR  
Q

TE 11