

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: | | | | | | | |

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7	0	1	8	9	A	R	A	N	0	1	2	14	15	0	0	-	0	0	0	0	0	-	0	0	13	26	4	1	1	1	1	4	57	CAT	58	15							
				LICENSEE CODE										LICENSE NUMBER										LICENSE TYPE																			
7	0	1	8	REPORT SOURCE 60										16	61	0	5	0	0	0	3	1	3	17	68	69	0	5	2	0	8	3	18	74	75	0	6	1	0	8	3	19	80
				DOCKET NUMBER										EVENT DATE										REPORT DATE																			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

DESCRIPTION AND PROBABLE CONSEQUENCES 10

On 5/20/83, while raising steam generator level for wet layup, emergency feedwater (EFW) pump P-7B indicated that the flow appeared degraded. The facility was in cold shutdown at the time of the occurrence. This occurrence is reportable per Technical Specification 6.12.3.2.c. No similar occurrences have been reported.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP SUBCODE		VALVE SUBCODE		REVISION NO	
0 9		H H 11		A 12		F 13		P U M P X X 14		B 15		Z 16		0	
7 8		9 10		11		12 13		13 18		19		20		32	
LER/RO REPORT NUMBER		EVENT YEAR		---		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE					
17		8 3		---		0 1 3		/		0 3		L		0	
21 22		23 24		25 26		27 28		29 30		31 32		33 34		35 36	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB		PRIME COMP. SUPPLIER	
X 19		X 19		Z 20		Z 21		0 0 0 0 22		Y 23		N 24		A 25	
33 34		35 36		37 38		39 40		41 42		43 44		45 46		47 48	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

[illegible]

FACILITY STATUS										METHOD OF DISCOVERY										DISCOVERY DESCRIPTION									
% POWER										OTHER STATUS																			
1 C 128										NA										A									
10 0 0 0 129										13										130 131									
ACTIVITY										CONTENT										Operator Observation									

ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
1 1 6 8	1 2 133	1 NA	1 35 1 NA
7 9	10	11	136
PERSONNEL EXPOSURES		44 45	80

PERSONNEL EXPOSURES										44	45	80
NUMBER				TYPE		DESCRIPTION						
1	1	7	1	0	0	0	37	12	38	1	NA	
7			8	9			11	12	13			139
PERSONNEL INJURIES												80

PERSONNEL INJURIES										80
NUMBER					DESCRIPTION					
1	0	0	0	40	NA					
9					11	12				141
LOSS OF OR DAMAGE TO FACILITY										80

80

LOSS OF OR DAMAGE TO FACILITY
TYPE DESCRIPTION
[1][9] [Z][42] NA
PUBLICITY

8306210003 830610
PDR ADCK 05000313
S PDR

143

[illegible]

NAME OF PREPARER _____ Patrick Rogers

PHONE: (501) 964-3100

IE22
1/1

LICENSEE EVENT REPORT

EXHIBIT A

LER No. 50-313/83-013/03L-0

Occurrence Date: 5/20/83

Cause Description and Corrective Actions (Continued):

Actions to prevent recurrence will be determined based on the results of the investigation.



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000
June 10, 1983

1CAN068309


Mr. W. C. Seidle, Chief
Reactor Project Branch #2
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 1
Docket No. 50-313
License No. DPR-51
Licensee Event Report
No. 83-013/03L-0

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 1 Technical Specification 6.12.3.2.c, attached is the subject report concerning flow degradation of emergency feedwater pump P-7B.

Very truly yours,


John R. Marshall
Manager, Licensing

JRM:RJS:s1

Attachment

cc: Mr. Richard C. DeYoung
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Norman M. Haller, Director
Office of Management & Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE-22