

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 8 9 L L S C 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 0 0 0 0 4 5 7 CAT 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T

0 1 7 8

REPORT SOURCE L 6 0 5 0 0 0 3 7 3 7 0 5 1 1 3 8 3 2 0 6 1 1 3 8 3 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES		CAUSE	CAUSE	COMP.	VALVE	
0	2	On May 15, 1983 at 0500 hours with Unit 1 in cold shutdown, the "B" VC chlorine				
0	3	detector tripped and would not reset. Since another train of the control room HVAC				
0	4	system was available and operating properly, the safety of the plant personnel was				
0	5	not affected.				
0	6					
0	7					
0	8					

7 8 9
80

SYSTEM CODE S G 11		CAUSE CODE E 12		CAUSE SUBCODE A 13		COMPONENT CODE E L E C O N 14				COMP. SUBCODE Z 15		VALVE SUBCODE Z 16					
EVENT YEAR 8 3 21 22		SEQUENTIAL REPORT NO. 0 5 1 24 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32									
ACTION TAKEN E 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 37 40		ATTACHMENT SUBMITTED Y 23		NPRO-6 FORM SUBL. N 24		PRIME COMP. SUPPLIER Z 25		COMPONENT MANUFACTURER Z 9 9 9 26 44 47	

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)

1	0	The cause of this occurrence was a loose ground wire on the circuit board. The loose
1	1	ground wire was promptly tightened under work request number L24705 and presently
1	2	functions properly.
1	3	
1	4	

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	B	28	0	0	0	29	A	31
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	Z	33	Z	34	NA			
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	0	0	0	37	Z	38	NA	
PERSONNEL INJURIES		NUMBER		DESCRIPTION					
1	8	0	0	0	40			NA	
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	Z	42			NA			
PUBLICITY ISSUED		DESCRIPTION							
2	0	N	44						

NRC USE ONLY  
 68 69 70

8306210192 830613  
 PDR ADOCK 05000373  
 S PDR

NAME OF PREPARER

J. J. Arand

PHONE: (815) 357-6761

NRC USE ONLY

8306210192 830613  
PDR ADOCK 05000373  
S PDR



**Commonwealth Edison**  
LaSalle County Nuclear Station  
Rural Route #1, Box 220  
Marseilles, Illinois 61341  
Telephone 815/357-6761

June 13, 1983

James G. Keppler  
Regional Administrator  
Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Sir:

Reportable Occurrence Report #83-051/03L-0, Docket #050-373 is being submitted to your office in accordance with LaSalle County Nuclear Power Station Technical Specification 6.6.B.2.(b), conditions leading to operation in a degraded mode permitted by a limiting condition for operation or plant shutdown required by a limiting condition for operation.

G. J. Diederich  
Superintendent  
LaSalle County Station

GJD/GW/rg

Enclosure

cc: Director of Inspection & Enforcement  
Director of Management Information & Program Control  
U.S. NRC Document Management Branch  
Inpo-Records Center  
File/NRC

JUN 15 1983

IE22  
1/1

- I. LER NUMBER 83-051/03L-0
- II. LASALLE COUNTY STATION: Unit 1
- III. DOCKET NUMBER: 050-373
- IV. EVENT DESCRIPTION:

On May 15, 1983 at 0500 hours with Unit 1 in cold shutdown, the "B" VC chlorine detector tripped and would not reset.

- V. PROBABLE CONSEQUENCES OF THE OCCURRENCE:

Since another train of the control room HVAC system was available and operating properly, the safety of the plant personnel was not affected.

- VI. CAUSE:

The cause of this occurrence was a loose ground wire on the circuit board. This is considered an isolated incident.

- VII. CORRECTIVE ACTION:

The loose ground wire on the circuit board was promptly tightened under work request number L24705 and presently functions properly.

Prepared by: John Arand