

NRC FORM 360
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 F L T P S 4 2 000-0000000-000 3 411111 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

CON'T 01 L 0 5 0 0 0 2 5 1 7 0 3 3 1 8 3 3 0 6 1 0 8 3 9

REPORT SOURCE 30 31 DOCKET NUMBER 38 39 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 On 3/31/83, while Unit 4 was in a refueling shutdown, we were notified by our

03 engineering staff of certain field discrepancies identified in the platform steel inside

04 containment. These discrepancies involve installation deficiencies for the bolting of

05 the platform framing steel at elevation 58'0" to the containment liner embedments.

06 This framing steel supports the containment emergency coolers and filters and

07 provides a working surface. This is reportable pursuant with T.S.6.9.2.a.9. The

08 health and safety of the public was not affected.

09

SYSTEM CODE Z Z 11 CAUSE CODE B 12 CAUSE SUBCODE C 13 COMPONENT CODE Z Z Z Z Z Z 14 COMP SUBCODE Z 15 VALVE SUBCODE Z 16

LER/RO REPORT NUMBER 17 EVENT YEAR 8 3 SEQUENTIAL REPORT NO. 0 0 1 OCCURRENCE CODE 0 1 REPORT TYPE X REVISION NO. 1

ACTION TAKEN B 18 FUTURE ACTION B 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 ATTACHMENT SUBMITTED Y 23 NPRO-4 FORM SUB N 24 PRIME COMP SUPPLIER Z 25 COMPONENT MANUFACTURER Z 9 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 An inspection on Unit 3 revealed significantly fewer deficiencies than Unit 4. Our

11 engineering department concluded that the Unit 3 steel platform connections are

12 acceptable under design loading conditions. The deficiencies in Unit 4 have been

13 corrected.

14

FACILITY STATUS H 15 % POWER 0 0 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY C 31 DISCOVERY DESCRIPTION Field Engineering observation 32

ACTIVITY, CONTENT RELEASED OF RELEASE Z 33 Z 34 N/A AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

PUBLICITY ISSUED DESCRIPTION N/A 45

NAME OF PREPARER Jesus Arias, Jr. PHONE: (305) 245-2910 Ext.200

IE22
11

USNRC REGION II
ATLANTA, GEORGIA

83 JUN 16 P 8:58



June 10, 1983
PNS-LI-83-406-1

Mr. James P. O'Reilly
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta Street N.W., Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-83-01

TURKEY POINT UNIT 4

DATE OF OCCURRENCE: MARCH 31 1983


TECHNICAL SPECIFICATION 6.9.2.a.9

CONTAINMENT PLATFORM

UPDATE REPORT NUMBER 1

The attached Licensee Event Report is being submitted to update our initial report dated April 14, 1983.

Very truly yours,


J. W. Williams, Jr.
Vice President
Nuclear Energy

JWW/PLP/js

Attachment

cc: Director, Office of Inspection and Enforcement (40)
Harold F. Reis, Esquire
File 933.1 TP

OFFICIAL COPY

IE 2211
PEOPLE...SERVING PEOPLE

Additional Cause Description and Corrective Actions

Based on the orientation of the slanted bolts, the relative location of the slots in the beam flanges, the holes in the beam seats, and the direction of the fracture plane in the sheared bolts; it has been concluded that the bolts were improperly installed with respect to the slots as shown on the design drawings. As a result, some of the bolts sheared due to the temperature expansion under normal operating conditions.

Unit 3 connections are scheduled to be restored to the design drawing configuration at the next refueling outage.