

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | P | A | T | M | I | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CONT

0 1 | REPORT SOURCE | X | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 8 | 9 | 7 | 0 | 8 | 3 | 1 | 8 | 2 | 8 | 0 | 6 | 0 | 6 | 8 | 3 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During long term cold shutdown, GPUN was notified by Wyle Labs that our PORV
0 3 | which had been shipped to them for refurbishment, was severely corroded. Some
0 4 | question exists if the valve could have performed its intended function if
0 5 | called upon in its present condition. A spare valve is installed at TMI-1 now
0 6 | and has functioned. Therefore, public health and safety were unaffected. This
0 7 | is not reportable per specific Technical Specification requirements. Information
0 8 | being provided as a special report.
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34

0 9 | SYSTEM CODE | C | A | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | D | 13 | COMPONENT CODE | V | A | L | V | E | X | 14 | COMP. SUBCODE | F | 15 | VALVE SUBCODE | B | 16 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
EVENT YEAR | 8 | 2 | 21 22 | SEQUENTIAL REPORT NO. | 0 | 1 | 1 | 23 24 25 26 | OCCURRENCE CODE | 9 | 9 | 27 28 29 | REPORT TYPE | X | 30 31 | REVISION NO. | 1 | 32 33 |
17 LER/RO REPORT NUMBER | 8 | 2 | 21 22 | ACTION TAKEN | X | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 22 23 24 | ATTACHMENT SUBMITTED | Y | 23 24 | NPPD-4 FORM SUB. | Y | 24 25 | PRIME COMP. SUPPLIER | N | 25 26 | COMPONENT MANUFACTURER | D | 2 | 4 | 3 | 26 27 28 |
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Corrosion has been attributed to acid sulfur compounds. See attachments for
1 1 | details of transport mechanism. Corrective action for this PORV was to remove
1 2 | from service and refurbish installed spare per updated LER 83-003/01T-1. No
1 3 | further corrective action is required.
1 4 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34

1 5 | FACILITY STATUS | X | 28 | % POWER | 0 | 0 | 0 | 29 | OTHER STATUS | NRC Order | 30 | METHOD OF DISCOVERY | D | 31 | DISCOVERY DESCRIPTION | Vendor Notification | 32 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
ACTIVITY RELEASED | Z | 33 | CONTENT OF RELEASE | Z | 34 | AMOUNT OF ACTIVITY | N/A | 35 | LOCATION OF RELEASE | N/A | 36 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | N/A | 39 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | N/A | 41 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | N/A | 43 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
PUBLICITY ISSUED | N | 44 | DESCRIPTION | N/A | 45 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34

8306210254 830606
PDR ADOCK 05000289
S PDR

N/A

NRC USE ONLY

NAME OF PREPARER C. J. Stephenson

PHONE (717) 948-8554