

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M I D I C C 1 2 0 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

CON'T 01 REPORT SOURCE 6 0 5 0 0 0 3 1 5 7 0 5 1 3 8 3 8 0 6 0 8 8 3 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

012 DURING NORMAL OPERATION, THE CONTROL ROOM EMERGENCY PRESSURIZATION CHARCOAL FILTER  
013 FIRE/TROUBLE ALARM WAS RECEIVED. ACTIONS WERE IMMEDIATELY TAKEN TO VERIFY THAT NO  
014 FIRE WAS ASSOCIATED WITH THE ALARM. THE FIRE PROTECTION DELUGE ISOLATION WAS CLOSED  
015 TO PERMIT INVESTIGATION INTO THE ALARM. THE EVENT WAS NON-CONSERVATIVE WITH RESPECT  
016 TO TECHNICAL SPECIFICATION 3.3.3.7 TABLE 3.3-10 ITEM 6. PRIOR TO THE DELUGE ISOLATION,  
017 THE ACTION REQUIREMENTS WERE MET. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED. THIS  
018 IS THE FIRST OCCURRENCE OF THIS TYPE.

019 A B 11 E 12 E 13 I N S T R U 14 E 15 Z 16

17 8 3 0 4 3 0 3 1 0

18 Z 19 Z 20 Z 21 0 0 0 0 22 Z 23 Y 24 A 25 A 1 9 8 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

110 INVESTIGATION REVEALED THAT THE RESISTANCE SETTINGS FOR THE PRE-ALARM AND ALARM WERE  
111 HIGH, THUS CAUSING THE ALARM. THE ALARM SETTINGS WERE ADJUSTED TO THEIR PROPER VALUES.  
112 THE SYSTEM WAS VERIFIED TO BE OPERATING CORRECTLY AND RETURNED TO SERVICE.

113  
114

115 E 28 1 1 0 0 29 NA 30 B 31 OPERATOR OBSERVATIONS 32

116 Z 33 Z 34 NA 35 NA 36

117 0 0 0 0 37 Z 38 NA 39

118 0 0 0 0 40 NA 41

119 Z 42 NA 43

120 N 44 NA 45

8306210267 830608  
PDR ADOCK 05000315  
S PDR

NAME OF PREPARER R. A. PALMER

PHONE (616) 465-5901

NRC USE ONLY

EPO 617-926