

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	1	L	L	S	C	1	2	0	10	-	0	0	0	0	0	0	0	0	3	4	1	0	0	0	4	1	5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	
LICENSEE CODE						LICENSE NUMBER								LICENSE TYPE				CAT 58									

01	L	6	0	5	0	0	0	0	3	7	3	7	0	5	12	0	8	13	2	0	6	1	6	8	13	9
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33
CONT		REPORT SOURCE		DOCKET NUMBER								EVENT DATE				REPORT DATE										

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On May 20, 1983, at 0730 hours it was discovered that a functional test of Drywell Air and Suppression Chamber Air/Water temperature had not been performed since the calibration was done on April 27, 1982. Technical Specification 4.6.2.1.c requires a channel functional test once per 31 days. The functional test was performed and found to be satisfactory. Therefore, the health and safety of the public was not affected.

09	S	C	11	D	12	Z	13	Z	Z	Z	Z	Z	14	Z	15	Z	16	17	8	3	0	5	4	0	3	L	0
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION	
18		19		20		21				22		23		24		25		26		27		28		29		30	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23		24		25		26		27		28		29	
17		18		19		20				21		22		23													




Commonwealth Edison
LaSalle County Nuclear Station
Rural Route #1, Box 220
Marseilles, Illinois 61341
Telephone 815/357-6761

June 16, 1983

James G. Keppler
Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Sir:

Reportable Occurrence Report #83-054/03L-0 Docket #050-373 is being submitted to your office in accordance with LaSalle County Nuclear Power Station Technical Specification 6.6.B.2.(c), observed inadequacies in the implementation of administrative or procedural controls which threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems.


G. J. Diederich
Superintendent
LaSalle County Station

GJD/GW/rg

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC Document Management Branch
Inpo-Records Center
File/NRC

JUN 20 1983

11
1E22

- I. LER NUMBER: 83-054/03L-0
- II. LASALLE COUNTY STATION: Unit 1
- III. DOCKET NUMBER: 050-373
- IV. EVENT DESCRIPTION:

On May 20, 1983, at 0730 hours it was discovered during a review of Technical Specification surveillance requirements that a functional test of Drywell Air and Suppression Chamber Air/Water Temperature had not been performed since the calibration was done on April 27, 1982. Technical Specification 4.6.2.1.c requires a channel functional test once per 31 days.

- V. PROBABLE CONSEQUENCES OF THE OCCURRENCE:

Immediately following the identification of the functional test deficiency, it was performed and found to be satisfactory. Therefore, the health and safety of the public was not affected.

- VI. CAUSE:

The calibration of this instrumentation was identified and satisfied per the Accident Monitoring Tech. Spec. requirements. The calibration and functional test of this instrumentation was also called for per a containment systems Tech. Spec. This requirement was never identified and incorporated into the computerized surveillance program by the Instrument Department.

- VII. CORRECTIVE ACTION:

The surveillance (LIS-CM-04) was revised to incorporate the monthly functional test. The test was then performed and found to be satisfactory. The monthly functional test has been incorporated into the computerized surveillance program. In addition, an on-site review was held to verify that no additional monthly functional test requirements have been overlooked. During this review an additional Instrument Surveillance Requirement Deficiency was found. Refer to LER #83-055/03L-0.

Prepared by: Alan F. Trainor