

## Docket 50-255

U. S. NUCLEAR REGULATORY COMMISSION

**LICENSEE EVENT REPORT**

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	P	A	L	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5			
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	57	CAT	58			59

0	1
---	---

**SOURCE**

REPORT SOURCE 01 6 05 0 0 0 2 5 5 7 0 6 0 3 8 3 8 0 6 1 3 8 3 9  
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

10

02 | LER 82-044 discusses a potential overload condition with MCC-1 and MCC-2  
03 | feeder breakers and cables when H<sub>2</sub> recombiners are loaded. At 2046, on  
04 | June 3, 1983, the H<sub>2</sub> recombiners were simultaneously loaded to their  
05 | respective MCC for routine surveillance testing contrary to a plant Stan-  
06 | ding Order (SO) which states that the H<sub>2</sub> recombiners will be operated  
07 | separately. The surveillance was successfully completed at 2325 on June 3,  
08 | Reportable per TS 6.9.2.a(6). No threat to public health/safety existed.

SYSTEM CODE [0][9]		CAUSE CODE [Z][Z]		CAUSE SUBCODE [D]		COMPONENT CODE [Z][Z][Z][Z][Z]				COMP. SUBCODE [Z]		VALVE SUBCODE [Z]							
7	8	9	10	11	12	13	13	13	13	13	14	15	16						
LER/RO REPORT NUMBER [17]		EVENT YEAR [8][3]		SEQUENTIAL REPORT NO. [0][3][9]		OCCURRENCE CODE [0][1]				REPORT TYPE [T]		REVISION NO. [0]							
21	22	23	24	25	26	27	28	29	30	31	32								
ACTION TAKEN [X]		FUTURE ACTION [G]		EFFECT ON PLANT [Z]		SHUTDOWN METHOD [Z]		HOURS [0][0][0][0]				ATTACHMENT SUBMITTED [N]		NPRD-4 FORM SUB [N]		PRIME COMP. SUPPLIER [Z]		COMPONENT MANUFACTURER [Z][9][9][9]	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50		

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Cause attributed to an inadequate surv proc which stated that the test

11 could indeed be performed simultaneously. An SE was standing SS watch and

12 did not recall the SO prior to initiation of the test. The surv proc will

13 be revised to prohibit simultaneous testing of H<sub>2</sub> recombiners. Review

14 regmts for SOs will be expanded to include all SROs who may stand SS watch.

FACILITY STATUS				% POWER				OTHER STATUS				METHOD OF DISCOVERY				DISCOVERY DESCRIPTION			
1	5	E	28	1	0	0	29	NA				B	31	Routine review					
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24		
ACTIVITY CONTENT				AMOUNT OF ACTIVITY				LOCATION OF RELEASE											
1	6	Z	33	Z	34	NA				NA									
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24		
PERSONNEL EXPOSURES				DESCRIPTION															
1	7	0	37	Z	38	NA													
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24		
PERSONNEL INJURIES				DESCRIPTION															
1	8	0	40	NA															
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24		
LOSS OF OR DAMAGE TO FACILITY				DESCRIPTION															
1	9	Z	42	NA															
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24		
PUBLICITY				DESCRIPTION															
2	0	N	44	NA															
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24		

8306270063 830613  
PDR ADOCK 05000255  
S PDR



Consumers  
Power  
Company

General Offices: 1945 West Parnall Road, Jackson, MI 49201 • (517) 788-0550

June 17, 1983

James G Keppler, Administrator  
Region III  
US Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

DOCKET 5C-255 - LICENSE DPR-20 -  
PALISADES PLANT - LICENSEE EVENT REPORT 83-39 (H<sub>2</sub> RECOMBINERS TESTED  
SIMULTANEOUSLY)

On the reverse please find Licensee Event Report 83-39 (H<sub>2</sub> Recombiners Tested  
Simultaneously which is reportable to the NRC per Technical Specification  
6.9.2.a(6)).

Brian D Johnson  
Staff Licensing Engineer

CC Director, Office of Nuclear Reactor Regulation  
Director, Office of Inspection and Enforcement  
NRC Resident Inspector - Palisades

JUN 20 1983

OC0683-0013A-NL02

11  
1E22