

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	A	P	P	S	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	9					14	15										25	26						30	57	CAT	58

CON'T

REPORT SOURCE L 6 0 5 0 - 0 2 9 3 7 0 5 1 5 8 3 8 0 6 1 3 8 3 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During an inspection of the CRD piping, a number of vent valve plugs were dis-
03 | covered to be missing. Leakage of control rod drive water past the valve seats
04 | into secondary containment could occur if the valves were left open following
05 | CRD line venting. No leaks were observed. This event caused no threat to the
06 | public health and safety.

0	7	
---	---	--

08 _____

7 8 9

SYSTEM CODE		CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE					COMP. SUBCODE	VALVE SUBCODE									
0	9	R	B	11	D	12	Z	13	V	A	L	V	E	X	14	G	15	L	16
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26

(17)	LER/RO REPORT NUMBER	[8][3]	[—]	SEQUENTIAL REPORT NO.	[0][2][6]	[/]	OCCURRENCE CODE	[0][3]	REPORT TYPE	[L]	[—]	REVISION NO.	[0]
		21 22	23		24 25 26	27		28 29		30	31		32
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	(22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER	(2)			
[A]	(18)[G]	(19)[Z]	(20)[Z]	(21)	[0][0][0][0]	(23)[N]	(24)[N]	(25)[Z]	(2)	[D][2][3][2]			
33 34	35	36	37 38 39 40	41	42	43	44	45	46	47			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS	
1 0	Inadequate procedures is the cause of this event. The majority of the missing
1 1	plugs were replaced and the remainder have been ordered to complete the replace-
1 2	ment. Applicable procedures will be modified to verify the as-left condition
1 3	of these valves.

1	4	
---	---	--

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
1	5	E	28	0	9	9	29	N/A	30	C	31	Piping walkdown	32

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z (33) Z (34) N/A

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

N/A

PERSONNEL EXPOSURES										
NUMBER		TYPE		DESCRIPTION						
1	7	0	0	0	37	Z	38	N/A		

PERSONNEL INJURIES		NUMBER		DESCRIPTION		(41)	
1	8	0	0	0	(40)	N/A	

7		8		9		11		12		80		
LOSS OF OR DAMAGE TO FACILITY												
TYPE										DESCRIPTION		
	9	Z	(42)	N/A								(43)

7	8	9	10											80
PUBLICITY														
ISSUED DESCRIPTION (45)														
2	0	N	(44)	N/A										
														NRC USE ONLY

NRC USE ONLY

G. G. Whitney

PHONE: (617) 746-7900

BOSTON EDISON COMPANY
800 BOYLSTON STREET
BOSTON, MASSACHUSETTS 02199

WILLIAM D. HARRINGTON
SENIOR VICE PRESIDENT
NUCLEAR

June 13, 1983

BECO. Ltr. #83-146

Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Docket No. 50-293
License DPR-35

Dear Sir:

The attached Licensee Event Report 83-026/03L-0 "Missing CRD Vent Valve Plugs", is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B.2.c.

If there are any questions on this subject, please contact us.

Respectfully submitted,

WD Harrington
William D. Harrington

WDH/mg

Enclosure: LER 83-026/03L-0

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Standard BECO. LER distribution

*FE22
1/1*