

## LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: | | | | | | | |

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[illegible]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

On 2/14/83, while performing engineered safeguards actuation system (ESAS) calibrations during the refueling outage, reactor coolant system (RCS) pressure transmitters PT-1040 (Channel 3) and PT-1020 (Channel 1) were found to be out of tolerance. The technical specifications (TS) trip setpoint is 1500 psi. A trip from the output of PT-1020 would have occurred at 1485.25 psi. A trip from the output of PT-1040 would have occurred at 1491.25 psi. This occurrence is reportable per T.S. 6.12.3.2.a. No similar occurrences have been reported regarding these transmitters; however, instrument drift was reported in LER's 313/74-008, 76-003 and 83-003.

7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE		COMP SUBCODE		VALVE SUBCODE		LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO																																																																																																																																																																					
7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	
7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	
7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78																																													

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
E   18	Z   19	Z   20	Z   21	0   0   0   0   22	N   23	Y   24	N   25	F   1   8   0   26
33	34	35	36	37 40	41	42	43	44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1	0	The cause of the occurrence was transmitter drift. The transmitters were recalibrated and left within the
1	1	allowable tolerance. The two transmitters are Foxboro Model E11GH-INM2, Bourdon type.
1	2	
1	3	
1	4	
7	8	
	9	

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION				
1	H	128	1	0	0	0	29	1	NA	30	1	B	31	1	Routine Surveillance	32
9			10				12	13		44		45		46		80

ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	6	2	34	NA	35	NA	36
7	8	9	10	11	44	45	80

PERSONNEL EXPOSURES										
NUMBER					TYPE		DESCRIPTION			
1	1	7	1	0	0	0	137	Z	138	NA
7	8	9	10	11	12	13				

PERSONNEL INJURIES									
NUMBER					DESCRIPTION				
1	2	3	4	5	6	7	8	9	10
1	8	0	0	0	40	NA			
7	8	9	11	12					

LOSS OF OR DAMAGE TO FACILITY	
TYPE	DESCRIPTION
1 9	1 Z 42 1 NA

[illegible]

NAME OF PREPARER Patrick Rogers

PHONE: (501) 964-3100