


LICENSEE EVENT REPORT

CONTROL BLOCK: 

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	9					14	15											25	26					30		57	CAT	58
LICENSEE CODE		LICENSE NUMBER																LICENSE TYPE											

CON'T

REPORT SOURCE: 01 L 6 05000318 7 051583 8 061383 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During Mode 2 operation while performing surveillance testing on main
0 3 | steam isolation valves (MSIV's), No. 21 MSIV stroked shut in 3.62 sec-
0 4 | onds, exceeding the 3.6 second limit of T.S. 3.7.1.5. While verifying
0 5 | adjustments had corrected the stroke time, the valve failed to shut via
0 6 | the hand switch. After cycling the switch 3 times the valve shut in
0 7 | 3.42 seconds. The valve was subsequently successfully shut 3 times with
0 8 | the handswitch and once using SGIS. Similar events: none.

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE	
0	9	C	D	X	Z	Z	Z	Z	Z	Z	Z	Z	Z				
7	8	9	10	11	12	13	14	15	16	17	18	19	20				
(17) LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
83		83		026		03		L		0							
21		22		23		24		25		26							
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
B		Z		C		Z		0004		N		N		Z		Z999	
33		34		35		36		37		41		42		43		44	
18		19		20		21		22		23		24		25		26	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Investigation found the arm loose for position switch 2-ZS-4043A (switch
1 1 provides full closed indication and signal to MSIV timer). Troubleshoot-
1 2 ing revealed no other problems with the MSIV and associated controls.
1 3 The arm was adjusted and tightened. All subsequent MSIV stroke testing
1 4 was satisfactory. A full stroke test will be performed at next shutdown.

8 9 FACILITY STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32

1 5 C 28 0 0 0 29 N/A B 31 Surveillance test

2 8 9 10 12 13 44 45 46 80

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 33 10 34 N/A

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

N/A

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7		37	38	N/A				

PERSONNEL INJURIES		NUMBER	DESCRIPTION
1	8	0000	(40) N/A

1	9	2	42	N/A	8306280352 830613 PDR ADOCK 05000318 S PDR
---	---	---	----	-----	--

2		0		N		44		N/A		NRC USE ONLY									
---	--	---	--	---	--	----	--	-----	--	--------------	--	--	--	--	--	--	--	--	--

NRC USE ONLY

NAME OF PREPARER P. A. Pieringer/L. S. Hinkle

PHONE: 301-269-4742/4986

BALTIMORE GAS AND ELECTRIC COMPANY

P.O. BOX 1475

BALTIMORE, MARYLAND 21203

NUCLEAR POWER DEPARTMENT
CALVERT CLIFFS NUCLEAR POWER PLANT
LUSBY, MARYLAND 20657

June 13, 1983

Mr. James M. Allan
Acting Regional Administrator
U. S. Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, PA 19406

Docket No. 50-318
License No. DPR 69

Dear Mr. Allan:

In accordance with Technical Specification 6.9 please find the attached thirty day report for LER 83-26/3L.

Should you have any questions regarding this report, we would be pleased to discuss them with you.

Very truly yours,

LBRussell
L. B. Russell
Plant Superintendent

LBR:LSH:bsb

cc: Director, Office of Management Information
and Program Control
Messrs: A. E. Lundvall, Jr.
J. A. Tiernan

IE22
1/1