


CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: 1										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)									
0 1 N Y J A F 1 2 0 0 - 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5 7 8 9 14 15 25 26 30 57 CAT 58																			
CON'T										0 1 L 6 0 5 0 0 0 3 3 3 7 0 5 2 0 8 3 8 0 6 2 0 8 3 9 7 8 60 61 68 69 74 75 80									
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10										0 2 While performing the monthly valve cycling surveillance test of 23 MOV-60 (HPCI 0 3 Outboard Containment Isolation Bypass Valve), the valve motor tripped on overload. 0 4 0 5 0 6 0 7 0 8 0 9									
0 9 7 8 9										SYSTEM CODE 2 3 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE V A L V E X 14 COMP. SUBCODE F 15 VALVE SUBCODE O 16 17 LER RO REPORT NUMBER 18 3 21 EVENT YEAR 18 3 22 SEQUENTIAL REPORT NO. 0 2 0 24 OCCURRENCE CODE 0 3 28 REPORT TYPE L 30 REVISION NO. 0 32 ACTION TAKEN A 33 FUTURE ACTION D 34 EFFECT ON PLANT Z 35 SHUTDOWN METHOD Z 36 HOURS 0 0 0 0 37 ATTACHMENT SUBMITTED Y 41 NPRD-4 FORM SUB. Y 42 PRIME COMP. SUPPLIER A 43 COMPONENT MANUFACTURER V 0 8 5 44									
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27										1 0 The valve packing was inspected; found to be extremely hard and creating stem binding, 1 1 it was replaced. After replacement and packing gland adjustment, the valve was stroked 1 2 successfully but the motor still had a high running current. The valve was declared 1 3 operable; however, daily cycling was performed to verify continued operability, until 1 4 the refueling outage now in progress commenced. The valve is to be inspected inter- 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50									
1 5 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50										FACILITY STATUS E 28 % POWER 1 0 0 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Operator Observation 32 ACTIVITY RELEASED Z 33 CONTENT Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43 PUBLICITY ISSUED N 44 DESCRIPTION NA 45									
2 0 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50										8306280486 830620 PDR ADOCK 05000333 S PDR NRC USE ONLY NAME OF PREPARER Roebert Peters PHONE: (315) 342-3840 X224									

James A. FitzPatrick
Nuclear Power Plant
P.O. Box 41
Lycoming, New York 13093
315 342.3840



June 20, 1983
JAFP-83-0644

Dr. Thomas E. Murley
Regional Administrator
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA 19406


REFERENCE: DOCKET NO. 50-333 Licensee Event Report: 83-020/03L-0

Dear Dr. Murley:

We have enclosed the referenced Licensee Event Report in accordance with Section 6.0 of Technical Specifications and USNRC Regulatory Guide 1.16.

If there are any questions concerning this report, please contact Mr. Robert Peters at (315)-342-3840, Extension 224.

Very truly yours,


CORBIN A. McNEILL, JR.

CAM:RP:slt
Enclosure

CC: USNRC Document Control Desk (1)
INPD Records Center, Atlanta, Georgia (1)
Internal Power Authority Distribution
NRC Resident Inspector
Document Control Center
LER/OR File

IE 22
11