

## LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 F L S L S 2 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1 4 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30CON'T  
01 REPORT SOURCE L 5 0 1 5 0 0 0 3 8 9 7 10 1 5 2 7 8 3 3 0 6 1 2 4 8 3 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During preoperational testing, problems developed with the three charging  
03 pumps and two out of three charging pumps were unavailable for a period of  
04 approximately 15 hours. However, one charging pump was always available  
05 and all three were restored to service well within the 72 hours allowed by  
06 Tech. Spec. 3.1.2.4. The health and safety of the general public were not  
07 affected by this event. This is the first LER of this type.

03 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

03 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP TUBCODE VALVE SUBCODE  
P C 11 E 12 B 13 V A L V E X 14 X 15 B 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

17 LER/RO REPORT NUMBER EVENT YEAR  
8 3 21 22  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB. PRIME COMP SUPPLIER COMPONENT MANUFACTURER  
C 13 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 A 25 C 7 1 1 0 26  
31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The "C" charging pump failed due to sealwater system gasket leakage. The  
11 "A" and "B" charging pumps failed due to charging pump relief valve failure.  
12 All three charging pumps were repaired and retested satisfactorily.

13 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

14 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

15 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
B 23 0 0 0 0 29 NA A 31 OPERATOR OBSERVATION  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE  
Z 33 Z 34 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  
0 0 0 37 Z 38 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

18 PERSONNEL INJURIES NUMBER DESCRIPTION  
0 0 0 40 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION  
Z 42 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

20 PUBLICITY ISSUED DESCRIPTION  
N 44 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

NAME OF PREPARER Dan West

PHONE (305) 465-3550 x3364

USNRC REGION II  
ATLANTA, GEORGIA

83 JUN 27 P1:11



June 24, 1983  
PNS-LI-83-446-1

Mr. James P. O'Reilly  
Regional Administrator, Region II  
U. S. Nuclear Regulatory Commission  
101 Marietta Street N.W., Suite 2900  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 389-83-16

ST. LUCIE UNIT 2

DATE OF OCCURRENCE: MAY 27, 1983

TECHNICAL SPECIFICATION 3.1.2.4

CHARGING PUMPS

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification on the subject occurrence.

Very truly yours,

A handwritten signature in dark ink, appearing to read "J. W. Williams, Jr.", is written over the typed name.

J. W. Williams, Jr.  
Vice President  
Nuclear Energy

JWW/PLP/js

Attachment

cc: Director, Office of Inspection and Enforcement (30)  
Harold F. Reis, Esquire  
File 933.1 SL

OFFICIAL COPY

IE22

PEOPLE ... SERVING PEOPLE