



GPU Nuclear Corporation
Post Office Box 388
Route 9 South
Forked River, New Jersey 08731-0388
609 971-4000
Writer's Direct Dial Number:

C321-94-2138
August 16, 1994


U. S. Nuclear Regulatory Commission
Att: Document Control Desk
Washington, DC 20555

Dear Sir:

Subject: Oyster Creek Nuclear Generating Station
Docket No. 50-219
Licensee Event Report 94-012

Enclosed is the Licensee Event Report 94-012.

If there are any questions please contact Mr. J. Rogers at 609.971.4893.



John J. Barton
Vice President and Director
Oyster Creek

JJB/JJR
Attachment

cc: Administrator, Region I
Senior Resident Inspector
Oyster Creek NRC Project Manager

9408290162 940816
PDR ADOCK 05000219
S PDR

GPU Nuclear Corporation is a subsidiary of General Public Utilities Corporation

JE22

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)

Oyster Creek Nuclear Generating Station

DOCKET NUMBER (2)

05000219

PAGE (3)

1 OF 4

TITLE (4)

Electromatic Relief Valve Setpoints Exceed Technical Specification Limits Due to Drift

| EVENT DATE (5) | | | LER NUMBER (6) | | | REPORT DATE (7) | | | OTHER FACILITIES INVOLVED (8) | | |
|--------------------|-----|------|---|-------------------|-----------------|------------------|-----|------|-------------------------------|---------------|--|
| MONTH | DAY | YEAR | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | MONTH | DAY | YEAR | FACILITY NAME | DOCKET NUMBER | |
| 07 | 24 | 94 | 94 | -- 012 -- | 0 | 08 | 16 | 94 | FACILITY NAME | DOCKET NUMBER | |
| | | | | | | | | | | 05000 | |
| | | | | | | | | | | 05000 | |
| OPERATING MODE (9) | | N | THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11) | | | | | | | | |
| | | | 20.402(b) | | | 20.405(c) | | | 50.73(a)(2)(iv) | | 73.71(b) |
| POWER LEVEL (10) | | 100 | 20.405(a)(1)(i) | | | 50.36(c)(1) | | | 50.73(a)(2)(v) | | 73.71(c) |
| | | | 20.405(a)(1)(ii) | | | 50.36(c)(2) | | | 50.73(a)(2)(vii) | | OTHER |
| | | | 20.405(a)(1)(iii) | | | X 50.73(a)(2)(i) | | | 50.73(a)(2)(viii)(A) | | (Specify in Abstract below and in Text, NRC Form 366A) |
| | | | 20.405(a)(1)(iv) | | | 50.73(a)(2)(ii) | | | 50.73(a)(2)(viii)(B) | | |
| | | | 20.405(a)(1)(v) | | | 50.73(a)(2)(iii) | | | 50.73(a)(2)(x) | | |

LICENSEE CONTACT FOR THIS LER (12)

NAME

Sylvain Schwartz

TELEPHONE NUMBER (Include Area Code)

609.971.4558

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

| CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NPRDS | CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NPRDS |
|-------|--------|-----------|--------------|---------------------|-------|--------|-----------|--------------|---------------------|
| | | | | | | | | | |
| | | | | | | | | | |

SUPPLEMENTAL REPORT EXPECTED (14)

| | | | | | | |
|---|---|----|-------------------------------|-------|-----|------|
| YES (If yes, complete EXPECTED SUBMISSION DATE). | X | NO | EXPECTED SUBMISSION DATE (15) | MONTH | DAY | YEAR |
|---|---|----|-------------------------------|-------|-----|------|

ABSTRACT (16) (Limit to 1400 spaces, i.e., approximately 15 single-spaced lines.)

On July 24, 1994, while performing an Electromatic Relief Valve (EMRV) Pressure Sensor surveillance, the as-found trip setpoints for the high pressure relief function on two EMRVs were above that specified in the Technical Specifications. The cause of this occurrence has been attributed to setpoint repeatability and instrument drift. The design setpoint repeatability allows the as-found value to be within 2.5 psig of the Technical Specification limit. Previous surveillance records indicate that these instruments can drift due to changing plant and ambient conditions.

This occurrence is considered to have minimal safety significance as the automatic depressurization function of the EMRVs is not affected by these pressure switches, all five EMRVs would have actuated to relieve pressure, the Isolation Condenser System and turbine bypass valves were fully operable, and manual operation of the valves was not affected. Additionally, a recent Technical Specification Change request was submitted demonstrating that an increase in the EMRV setpoints of 15 psig would have no impact on safety. The pressure switches were adjusted to actuate within the Technical Specification limit.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION
APPROVED BY OMB NO. 3150-0104
EXPIRES 5/31/95

| FACILITY NAME (1) | DOCKET NUMBER (2) | LER NUMBER (6) | | | PAGE (3) |
|----------------------|-------------------|----------------|----------------------|--------------------|----------|
| Oyster Creek, Unit 1 | 05000219 | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | 2 OF 4 |
| | | 94 | -- 012 -- | 0 | |

DATE OF DISCOVERY

The condition described within this report was discovered during the performance of a routine surveillance test on July 24, 1994.

IDENTIFICATION OF OCCURRENCE

During the performance of an Electromatic Relief Valve (EIRV) Pressure Sensor Test and Calibration surveillance, two relief valves had high pressure relief setpoints above that specified in the Plant Technical Specifications. This event is considered to be reportable as defined in 10 CFR 50.73(a)(2)(i).

CONDITIONS PRIOR TO DISCOVERY

The reactor was at approximately 100% power. System pressures and temperatures were normal for full power operation.

DESCRIPTION OF OCCURRENCE

On July 24, 1994, while performing the Electromatic Relief Valve (EMRV) Pressure Sensor Test and Calibration surveillance, the as-found trip setpoint for the high pressure relief function on two EMRVs was above that specified in the Technical Specifications. The Technical Specification limit for the B EMRV pressure sensor is 1104.5 psig and 1082.2 psig for the D EMRV pressure sensor. Test results determined the setpoint for the B EMRV was at 1105.0 psig and the setpoint for the D EMRV was at 1086.0 psig.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION
APPROVED BY OMB NO. 3150-0104
EXPIRES 5/31/95

| FACILITY NAME (1) | DOCKET NUMBER (2) | LER NUMBER (6) | | | PAGE (3) |
|----------------------|-------------------|----------------|----------------------|--------------------|----------|
| Oyster Creek, Unit 1 | 05000219 | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | 3 OF 4 |
| | | 94 | -- 012 -- | 0 | |

APPARENT CAUSE OF OCCURRENCE

The cause of this occurrence is attributed to instrument setpoint repeatability and instrument drift due to changing plant and ambient conditions. The tolerance between the as-left instrument setpoint and the Technical Specification is 10 psig. The design accuracy for these sensors is ± 7.5 psig. Therefore, design setpoint repeatability allows the "as found" value to be within 2.5 psig of the Technical Specification limit.

A review of previous surveillance records indicated that these instruments frequently undergo additional drift during changes in plant and ambient conditions. A 2.5 psig additional drift beyond the 7.5 psig design tolerance would cause the instrument setpoint to exceed the Technical Specification limit.

ANALYSIS OF OCCURRENCE AND SAFETY SIGNIFICANCE

The EMRVs are part of the Automatic Depressurization System (ADS) (EIIS BM). This system is designed to depressurize the Reactor Coolant System (EIIS AB) during small break Loss-of-Coolant Accident conditions so that the low pressure Core Spray System (EIIS BM) can inject. The ADS function of the EMRVs is not affected by these switches. The EMRVs also provide pressure control for the reactor pressure vessel. Together with the high pressure scram function and the Isolation Condenser System (EIIS BL), the EMRVs limit pressure in the Reactor Coolant System during high pressure transients.

This occurrence is considered to have minimal safety significance as: 1) the ADS function of the EMRVs is not affected by these pressure switches, therefore, all five EMRVs would have actuated to relieve pressure; 2) the Isolation Condenser System and turbine bypass valves were fully operable; and 3) manual operation of the EMRVs was not affected. The evaluation performed in support of a Technical Specification Change Request increasing the subject setpoints concluded that raising the existing Technical Specification setpoints by 15 psig has no adverse effect on plant safety. The drift experienced by the sensors in this report is much less than 15 psig above the Technical Specification setpoint (0.5 psig and 3.8 psig for the B and D EMRV, respectively). In addition, the reactor safety valves are designed to prevent reaching the Reactor Coolant System pressure safety limit of 1375 psig on a complete loss of EMRV relief capability.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATIONU.S. NUCLEAR REGULATORY COMMISSION
APPROVED BY OMB NO. 3150-0104
EXPIRES 5/31/95

| FACILITY NAME (1) | DOCKET NUMBER (2) | LER NUMBER (6) | | | PAGE (3) |
|----------------------|-------------------|----------------|----------------------|--------------------|----------|
| Oyster Creek, Unit 1 | 05000219 | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | 4 OF 4 |
| | | 94 | -- 012 -- | 0 | |

CORRECTIVE ACTION

The pressure switches were immediately adjusted to actuate within the Technical Specification limits. A Technical Specification Change Request raising the subject setpoint by 15 psig was previously submitted to the NRC. This action will minimize the risk of exceeding the Technical Specification limit.

SIMILAR EVENTS

| | |
|-----------|--|
| LER 81-40 | EMRV Pressure Sensor Test and Calibration |
| LER 81-51 | EMRV High Pressure Sensor |
| LER 81-57 | Reactor High Pressure Switch "B" EMRV |
| LER 82-24 | EMRV Switch Out of Technical Specification Limit |
| LER 90-10 | EMRV High Pressure Relief Setpoints Exceed Technical Specification Limit Due to Drift |
| LER 92-12 | EMRV High Pressure Relief Setpoints Exceed Technical Specification Limit Due to Drift |
| LER 94-08 | EMRV High Pressure Relief Setpoints Exceed Technical Specification Limit Due to Drift |