

LICENSEE EVENT REPORT

Attachment to AECM-83/0183

Page 1 fo 2

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M S G G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 37 CAT 58

CON'T

0 1 REPORT SOURCE L 6 0 5 0 0 0 4 1 6 7 0 3 1 1 8 3 8 0 3 2 4 8 3 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 On March 11, 1983, Operations discovered that fire watches were not con-
0 3 ducted in two areas of fire detection zone 2-19 as required by action
0 4 (a) of T.S.3.3.7.9. An LCO had been entered on February 27, 1983 for
0 5 zone 2-19. The event had no effect on the health and safety of the
0 6 public and did not constitute a threat to plant safety. This is reported
0 7 pursuant to T.S.6.9.1.12.b. and T.S.6.9.2.

0 8

0 9 SYSTEM CODE CAUSE CODE CAUS. SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
A B 11 A 12 A 13 I N S T R U 14 E 15 Z 16
7 8 9 10 11 12 13 18 19 20
17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
8 3 0 5 8 0 1 T 0
21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
X 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 A 25 H 2 6 0 26
33 34 35 36 37 40 41 42 43 44 45

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The fire detection zone consists of six areas on the 139 ft. elevation
1 1 of the Auxiliary Building. Due to personnel oversight, two of the areas
1 2 were omitted from the fire watch checksheet. The areas were immediately
1 3 added to the list upon discovery. This is an interim report. An update
1 4 will be submitted by April 30.

1 5 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32
X 28 0 0 0 29 Core Alteration A 31 Operator Observation
7 8 9 10 12 13 44 45 46 88

1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
Z 33 Z 34 NA
7 8 9 10 11 44 45 88

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
0 0 0 37 Z 38 NA
7 8 9 11 12 13 88

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION 41
0 0 0 40 NA
7 8 9 11 12 88

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43
Z 42 NA
7 8 9 10 88

2 0 PUBLICITY ISSUED DESCRIPTION 45
N 44 NA
7 8 9 10 88

8304010551 830324
PDR ADOCK 05000416
S PDR

NRC USE ONLY

NAME OF PREPARER Ron Byrd

PHONE:

SUPPLEMENTARY INFORMATION TO
LER 83-058/01 T-0

Mississippi Power & Light Company
Grand Gulf Nuclear Station - Unit 1
Docket No. 50-416

Technical Specification Involved: 3.3.7.9
Reported Under Technical Specification: 6.9.1.12.b and 6.9.2

Event Narrative:

On February 27, 1983, fire detection Zone 2-19 (139 feet, Auxiliary Building) was declared inoperable due to a continuous alarm. An LCO was entered and an hourly fire watch was established pursuant to T.S.3.3.7.9. On March 11, Operations discovered that two of the six areas in the zone were inadvertently omitted from the fire watch checksheet. These areas were 1A323 (SGTS 'A' area) and 1A324 (HVAC equipment area).

The HVAC equipment area is open to an adjacent area which was under the fire watch. A fire in this area would likely have been detected.

The SGTS 'A' room is an enclosed area. The fire detection for this room was required to be operable from February 27 to March 11 due to core alterations being performed. SGTS is required to be operable by T.S.3.6.6.3 during core alterations.

The two areas had been entered on the LCO report as requiring a fire watch. The room numbers were not transferred to the fire watch checksheets due to oversight. The room numbers were immediately added to the list upon discovery.

The LCO is still in effect. Estimated restoration is by March 25. An update will be submitted by April 30, 1983. This is reported to comply with T.S.6.9.1.12.b and T.S.6.9.2.