

Alabama Power Company  
40 Inverness Center Parkway  
Post Office Box 1295  
Birmingham, Alabama 35201  
Telephone 205 868-5581

W. G. Hairston, III  
Senior Vice President  
Nuclear Operations

December 20, 1990



Docket No. 50-364


U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D. C. 20555

Joseph M. Farley Nuclear Plant - Unit 2  
Special Report No. 90-011, Fire Detection  
Instrumentation Inoperable For More Than Fourteen Days

Gentlemen:

In accordance with the requirements of Technical Specification 3.3.3.9, the enclosed Special Report No. 90-011, Unit 2, is submitted.

Respectfully submitted,

  
W. G. Hairston, III

WGH,III/DEM:sh 26.39

Enclosure

cc: Mr. S. D. Ebner  
Mr. S. T. Hoffman  
Mr. G. F. Maxwell

9012260260 901220  
PDR ADOCK 05000364  
S PDR

400440

JE22  
1/1

Special Report No. 90-011, Unit 2  
Fire Detection Instrumentation Inoperable For More Than Fourteen Days

At 2236 on 11-17-90, during a refueling outage, all smoke detectors in room 2172 were disabled to allow welding in the room. Due to the scope of the work, the detectors were not returned to service within fourteen days. If less than two smoke detectors are operable in room 2172, Technical Specification 3.3.3.9 requires that the inoperable smoke detectors be restored to operable status within 14 days, or a Special Report must be submitted within the following 30 days. Therefore, this Special Report is being submitted.

All the smoke detectors in room 2172 were returned to service on December 5, 1990. Technical Specification action statement requirements were met for the inoperable smoke detectors.

DEMc:sh 26.39