

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

PHONE (205) 729-0841

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 8316 Technical Specification Involved Table 3.2.F

Reported Under Technical Specification 6.7.2.b.(2)* Date Due NRC 4/1/83

Event Narrative:

Units 1 and 3 were operating normally at 94 and 100% power respectively. Unit 2 was in a refueling outage. Only unit 3 was affected by this event. Remote reactor water level indicator LI-3-46A was observed to be fluctuating erratically and declared inoperable. LI-3-46A and LI-3-46B comprise the reactor water level surveillance instrumentation. Tech. Spec. Table 3.2.F allows continued operation for 30 days when indication is reduced by one. The indicator was replaced; however, the erratic indication persisted. The problem was resolved by a calibration adjustment per SCI-225. There was no effect on public health and safety. Redundant indication was available and operable. This is considered a random event and no further recurrence control is required.

* Previous Similar Events:

None

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

Revision: JRP