

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M I D I C C 1 2 0 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5

CON'T 01 REPORT SOURCE L 6 0 5 0 0 0 0 3 1 1 5 7 0 3 1 1 4 8 3 8 0 3 3 1 8 3 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 DURING ROUTINE SURVEILLANCE OF THE FIRE DETECTION INSTRUMENTATION AND CARDOX SYSTEM

03 IT WAS FOUND THAT THE CONTROL ROOM AIR CLEANUP CHARCOAL FILTER (1-HV-ACRF) DETECTION

04 SYSTEM WAS INOPERABLE. THIS EVENT WAS NON-CONSERVATIVE WITH RESPECT TO TECHNICAL SPEC

05 IFICATION 3.3.3.7 TABLE 3.3-10. THE ACTION REQUIREMENTS WERE MET. THIS IS THE FIRST

06 OCCURRENCE OF THIS TYPE. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.

07

08

09

09 SYSTEM CODE A B 11 CAUSE CODE E 12 CAUSE SUBCODE G 13 COMPONENT CODE I N S T R U 14 COMP SUBCODE E 15 VALVE SUBCODE Z 16

17 LER/RO REPORT NUMBER 8 3 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 INVESTIGATION REVEALED THAT THE THERMISTOR STRING HAD A HOLE ARCED THROUGH IT AND THE

11 ELECTRONIC DETECTION CIRCUIT BOARD ASSOCIATED WITH THE THERMISTOR STRING HAD FAILED.

12 THE CAUSE FOR THE ARCING OR THE CKT. BOARD FAILURE COULD NOT BE DETERMINED. BOTH THE

13 THERMISTOR STRING AND THE CKT. BOARD MFG.'d BY ALISON CONTROL INC. WERE REPLACED. THE

14 FIRE DETECTION SYS. OPERABILITY WAS VERIFIED TO BE CORRECT AND RETURNED TO SERVICE.

15 FACILITY STATUS E 28 1 0 0 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

NAME OF PREPARER R. A. PALMER

PHONE 616-465-5901

8304110197 830331
PDR ADOCK 05000315
S PDR

NRC USE ONLY