



**PERRY NUCLEAR POWER PLANT**

10 CENTER ROAD  
PERRY, OHIO 44081  
(216) 259-3737

Mail Address:  
PO. BOX 97  
PERRY, OHIO 44081

**Robert A. Stratman**  
VICE PRESIDENT - NUCLEAR

September 8, 1994  
PY-CEI/NRR-1857L

U.S. Nuclear Regulatory Commission  
Document Control Room  
Washington, D.C. 20555

Perry Nuclear Power Plant  
Docket No. 50-440  
Inoperable Accident Monitoring  
Instrumentation - Special Report

Gentlemen:

Attached is a Special Report concerning inoperable Accident Monitoring Instrumentation. This report satisfies the requirements of Perry Technical Specifications 3.3.7.5 and 6.9.2.

If you have questions or require additional information, please contact Mr. James D. Kloosterman, Manager - Regulatory Affairs, at (216) 280-5833.

Very truly yours,

A handwritten signature in dark ink, appearing to read 'Robert A. Stratman', with a stylized flourish at the end.

RAS:DHL:sc

cc: NRC Project Manager  
NRC Resident Inspector Office  
NRC Region III

130072

Operating Companies  
Cleveland Electric Illuminating  
Toledo Edison

9409160270 940908  
PDR ADDCK 05000440  
S PDR

JE22

On August 25, 1994, at 1120, the Offgas Ventilation Exhaust Post Accident Radiation Monitor was declared inoperable for performance of preventative maintenance and calibration, as required by Technical Specifications. Technical Specification 3.3.7.5 requires submittal of a Special Report within 14 days if the radiation monitor is not restored to operable within 72 hours. The 72 hour limit was exceeded on August 28, 1994 at 1120. In accordance with Technical Specification Action 81, pre-planned alternate monitoring methods were initiated. All aspects of Technical Specifications were met.

The Offgas Ventilation Exhaust Post Accident Radiation Monitor monitors the Offgas ventilation exhaust effluent airborne radiation during accident conditions. The sample is drawn from the normal range atmosphere radiation monitor isokinetic sampler. The sample passes through one of three particulate/iodine channels and then through a sample pump and a gas sample chamber. The gas sample chamber has two detectors, one each for intermediate and high range airborne radiation levels. Signals from the sample panel are sent to a microcomputer for processing. The signals provide indication to the control module in the Unit 1 Control Room.

The preventative maintenance being performed was replacement of a flow control circuit card in the sampler panel. Following replacement on August 26, 1994, the new circuit card would not calibrate properly. The work was postponed until August 29, 1994, causing the 72 hour limit to be exceeded. A condition report has been initiated to investigate the circumstances which resulted in postponing the work.

Further troubleshooting showed that the replacement flow control card was faulty. With no other replacement flow control cards available it was decided to reinstall and calibrate the original circuit card. Following installation, the original card operated intermittently. Troubleshooting determined the signal was being grounded through the circuit card mounting screws. The original mounting screws were specified as nylon on the bill of material, but were found to be steel. Nylon screws have been ordered with a scheduled delivery date to support returning the Offgas Ventilation Exhaust Radiation Monitor to operable on September 12, 1994.