



Entergy Operations

Entergy Operations, Inc.

P.O. Box 756

Port Gibson, MS 39150

Tel 601-437-6408

W. T. Cottle

Vice President

Operations

Grand Gulf Nuclear Station

April 12, 1991

U.S. Nuclear Regulatory Commission
Mail Station P1-137
Washington, D.C. 20555

Attention: Document Control Desk

Gentlemen:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-29
Special Report 89-001-01
Update to Diesel Generator Failure
to Load During Test

GNRO-91/00059

On February 1, 1989 at approximately 1020 during the performance of the monthly functional surveillance, the output breaker for Diesel Generator 12 failed to close while attempting to parallel the generator with an energized bus. The diesel generator was declared inoperable and a maintenance investigation was conducted. The cause of the incident was determined to be a malfunction of a tachometer transmitter. The transmitter was replaced and the diesel generator functional test was successfully completed by 2215 on February 1.

The tachometer transmitter malfunction would not have prevented the diesel generator breaker from closing in the emergency operating mode. The diesel generator is equipped with two redundant start circuits. During non-emergency starts, the transmitter in each circuit must function to provide a breaker closing permissive when paralleling the generator to the grid. During an emergency start, either tachometer transmitter can provide the breaker closing permissive signal. Therefore, the unsuccessful load attempt is not considered a valid test or failure in accordance with position C.2.e(2) of Regulator Guide 1.108. The testing frequency of Diesel Generator 12 remains at once per 31 days in accordance with the schedule of Technical Specification Table 4.8.1.1.2-1.

The failure of the transmitter (Airpax Model number 080-321-2112) was attributed to an excessive voltage input to the transmitter during periods of battery equalization. Since February 1, 1989, GGNS has not experienced any similar failures.

SR890101/SCMPFLR - 1

9104190203 910412
PDR ADOCK 05000416
S PDR

IED2
110

April 12, 1991
GNRO-91/00059
Page 2 of 3

Original plans were to install transmitters with a higher voltage input range to prevent recurrence of the failure. Following discussions with the supplier, it was determined that a qualified transmitter with a higher voltage input range was not available from any source.

GGNS was supplied with an upgraded version of the original transmitter. The current rating of the internal relays for this type of transmitter was found to be below the actual current flow for our application. This deficiency was documented on a Material Nonconformance Report.

GGNS installed the upgraded transmitters and made wiring changes to resolve the current rating deficiency with a Minor Change Package during RFO4 on the Division 1 Diesel Generator. The wiring changes reduce the current load on the internal relays to improve reliability.

GGNS currently plans to install the upgraded transmitters and make wiring changes to the Division 2 Diesel Generator during RFO5, in accordance with the Minor Change Package.

Yours truly,

WTC/cg

WTC/cg

cc: Mr. D. C. Hintz
Mr. R. B. McGehee
Mr. N. S. Reynolds
Mr. H. L. Thomas
Mr. J. L. Mathis

Mr. Stewart D. Ebner
Regional Administrator
U.S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 2900
Atlanta, Georgia 30323

Mr. L. L. Kintner, Project Manager
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Mail Stop 11D21
Washington, D.C. 20555

April 12, 1991
GNRO-91/00059
Page 3 of 3

bcc: Mr. C. W. Angle
Mr. M. A. Dietrich
Mr. C. R. Hutchinson
Ms. F. K. Mangan
Mr. M. J. Meisner
Mr. G. W. Muench
Mr. T. E. Reaves
MR. R. Ruffin
Mr. F. W. Titus
Mr. G. A. Zinke
SRC Secretary
File (LCTS) (2)
File (RPTS)
File (NL)
File (Central) (3)