

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
400 Chestnut Street Tower II

April 4, 1983

BLRD-50-438/82-60

U.S. Nuclear Regulatory Commission  
Region II  
Attn: Mr. James P. O'Reilly, Regional Administrator  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNIT 1 - WESTINGHOUSE LOW VOLTAGE SWITCHGEAR -  
BLRD-50-438/82-60 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector Don Quick on August 23, 1982 in accordance with 10 CFR 50.55(e) as NCR 1948. This was followed by our first interim report dated September 21, 1982. Enclosed is our second interim report. We expect to submit our next report by August 4, 1983.

If you have any questions concerning this matter, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*L. M. Mills*  
L. M. Mills, Manager  
Nuclear Licensing

Enclosure

cc: Mr. Richard C. DeYoung, Director (Enclosure)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Records Center (Enclosure)  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

8304110644 830404  
PDR ADOCK 05000438  
S PDR

OFFICIAL COPY

IE 27

ENCLOSURE

BELLEfonte NUCLEAR PLANT UNIT 1  
WESTINGHOUSE LOW VOLTAGE SWITCHGEAR  
NCR 1948  
BLRD-50-438/82-60  
10 CFR 50.55(e)  
SECOND INTERIM REPORT

Description of Deficiency

The affected low-voltage switchgear was supplied by Westinghouse, Pittsburgh, Pennsylvania. During a test of the HVAC chilled water pump, the 1EX2-A switchgear failed to trip when power was lost inadvertently. Upon restoration of power, the pump motor was activated without benefit of component cooling water or lubricant because the low-voltage switchgear associated with these systems did trip thereby preventing unintentional reenergization. Consequently, the HVAC chilled water pump was burned out.

A preliminary investigation revealed that the probable cause of the deficiency was the insertion of a DC fuse block incorrectly in the low-voltage switchgear. The incorrect configuration resulted in an open circuit which, in turn, prevented the switchgear from tripping.

Interim Progress

TVA has determined that the DC fuse blocks will be marked with paint to indicate the correct position for each fuse block. This will significantly reduce the possibility of operator error when the fuse blocks are re-inserted.

TVA is evaluating this deficiency to determine the root cause of the nonconformance and the actions required to prevent recurrence. TVA will provide a final report upon completion of this evaluation.