

## LICENSEE EVENT REPORT

CONTROL BLOCK: 

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5			
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	4	57	CAT	58	5

CON'T

0 1 7 8  
REPORT SOURCE L 6 0 5 0 0 0 2 2 0 7 0 3 1 5 8 3 8 0 3 2 3 8 3 9  
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | SEE ATTACHED SHEET

0	3	
---	---	--

05 | Page

0	6	
---	---	--

08 | \_\_\_\_\_

7 8 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

0 9 C G 11 E 12 E 13 I N S T R M 14 I 15 Z 16

9 10 11 12 13 14 15 16 17 18 19 20

(17) LER/RO REPORT NUMBER	EVENT YEAR 83	SEQUENTIAL REPORT NO. 005	OCCURRENCE CODE 01	REPORT TYPE T	NO. 0
ACTION TAKEN E	FUTURE ACTION G	EFFECT ON PLANT Z	SHUTDOWN METHOD Z	HOURS 0000	ATTACHMENT SUBMITTED Y
(18)	(19)	(20)	(21)	(22)	(23)
(33)	(34)	(35)	(36)	(37)	(40)
NPRD-4 FORM SUB. N	PRIME COMP. SUPPLIER N	COMPONENT MANUFACTURER G080	(24)	(25)	(26)
(42)	(43)	(44)	(45)	(46)	(47)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	SEE ATTACHED SHEET.
---	---	---------------------

1	1	
---	---	--

1 2 |

1	3	
---	---	--

1	4	
---	---	--

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	D	0	0	0	NA			A	Operator Observation		

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)  
1 6 L (33) M (34) C060  
LOCATION OF RELEASE (36)  
Cleanup Filter Sludge Tank to Rx. Bldg.

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION (39)				
1	2	10	10	10	(37)	Z	(38)	NA	

PERSONNEL INJURIES  
NUMBER DESCRIPTION (41)

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

8304110775 830325  
BACK 05000220

1	2	3	4	5	6	7	8	9	10	11	12
LOSS OF OR DAMAGE TO FACILITY (43)											
TYPE DESCRIPTION											

TYPE		DESCRIPTION
1	9	(L) (42) Reactor Building normal ventilation system until area is cleaned.

		PUBLICITY		NRC USE ONLY
ISSUED		DESCRIPTION	(45)	
2	0	Y(44)	3/15/83 reported to media a spill in a contained area	

7 8 9 (10) Robert G. Randall GR (11) (315) 349-2445

NRC USE ONLY

(315) 349-2445

## LICENSEE EVENT REPORT

LER 83-05

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

During a major maintenance outage with the core off-loaded, the Reactor Building ventilation system isolated and emergency ventilation system initiated due to a release of radioactive contaminants in the Reactor Building ventilation system. The systems all operated in accordance with Tech. Spec. Table 3.6.2j. The radioactive contaminants, fission and corrosion products, were released when the Reactor Water Cleanup System's filter sludge tank overflowed. The quantity and activity of the release to the Reactor Building could not be accurately determined because of the area of distribution within the Reactor Building. Based on stack effluent monitoring, there was no release from the Station. LER 82-03 reported a similar experience.

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

The cause of this event was the failure of the cleanup filter sludge tank level indicator. The cleanup system, which has been in dry layup for several months, was being filled, and the cleanup filters were being flushed into the filter sludge tank. The corrective actions stated in LER 82-03 were fulfilled, ie., the tank was pumped down and the air supply to the bubbler indicator was checked, and the indication appeared to be working. Flushing was done in short steps while an operator observed the indicator with instructions to stop the flushing operation at 30% full. At an indication of 26% full, the tank overflowed through the vent line into the Reactor Building ventilation duct, causing the duct radiation monitors to alarm, isolate normal ventilation and initiate the emergency ventilation system.

The Control Room operators ordered a Reactor Building evacuation and the flushing operation was immediately secured. The contaminated water leaked out of the ducting and spread to several locations in the Reactor Building. No one was contaminated by the incident.

The future action to prevent reoccurrence will be to require level indicator calibration prior to adding water to the filter sludge tank. Modifications to improve the system will also be investigated.