

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6
					1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	
7		8		9		10		11		12		13		14		15		16		17		18		19		20		21	

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

0	1	L	6	0	5	0	0	0	3	1	8	7	0	3	0	3	8	3	8	0	3	3	1	8	3	9			
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	
7		8		9		10		11		12		13		14		15		16		17		18		19		20		21	

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation an engineering evaluation determined that a

0 3 support was required on auxiliary HPSI header relief valve (RV-417) to

0 4 ensure auxiliary header integrity during a seismic event. Subsequently,

0 5 the effected HPSI header was declared inoperable (T.S. 3.5.2). The sup-

0 6 port was installed and the header declared operable within 36 hours

0 7 after entry into the action statement. The redundant HPSI header re-

0 8 mained operable during this event. Similar events: none.

7 8 9

0	9	S	F	11	D	12	Z	13	S	U	P	O	R	T	14	A	15	Z	16
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26
7		8		9		10		11		12		13		14		15		16	

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
(17) LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
F 18 Z 19 Z 20 Z 21 0 0 0 0 0 N 23 N 24 A 25 G 2 5 7 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Hanger was not reinstalled due to lack of instruction in a modification

1 1 work package regarding hangers and failure to field inspect the modifi-

1 2 cation. Plant instructions now describe a process involving a field re-

1 3 view by a work group supervisor, a provision not in effect at the time

1 4 of the modification. No other action necessary.

7 8 9

1	5	E	28	1	0	0	29	N/A	D	31	Notification from Bechtel
7	8	9	10	11	12	13	14	15	16	17	18
7		8		9		10		11		12	

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
1 6 Z 33 Z 34 N/A N/A
7 8 9 10 11 12 13 14 15 16 17 18
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION PERSONNEL INJURIES NUMBER DESCRIPTION
1 7 0 0 0 37 Z 38 N/A
7 8 9 10 11 12 13 14 15 16 17 18
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
1 9 Z 42 N/A
7 8 9 10 11 12 13 14 15 16 17 18
PUBLICITY ISSUED DESCRIPTION N/A
2 0 N 44
7 8 9 10 11 12 13 14 15 16 17 188304120425 830331
PDR ADOCK 05000318
S PDR

NRC USE ONLY

NAME OF PREPARER P. Pieringer/H. M. Carpenter

PHONE: (301) 269-4742/4816